UNITED STATES UNITED STATES SUBMIT IN TRIPLICATES DEPARTMENT OF THE INTERIOR (Other, instructions on re-

SHOOTING OR ACIDIZING

(Other) _

Form approved, Budget Bureau No. 42-R1424.

ABANDONMENT*

	GE(GICAL SURVEY	5. LEASE DESIGNATION AND SERIAL NO. NM 4609		
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTER		
1.	OIL X GAS OTHER	7. UNIT AGREEMENT NAME		
2.	NAME OF OPERATOR	S. FARM OR LEASE NAM	rw	
	MEWBOURNE OIL COMPANY	-		
3.	ADDRESS OF OPERATOR	Federal 9. WELL NO.	E.,	
	P. O. Box 7698, Tyler, TX 75711		4	
4.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT		
1650' fromNorth Line and 2310' from East Line		Undesignated 11. SEC., T., R., M., OR BUK. AND SURVEY OR AREA 27-T18S-R32E		
14.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)			
	3737.9 GL	12. COUNTY OR PARISH	NM NM	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or	Other Data	<u> </u>	
	NOTICE OF INTENTION TO	SUBSEQUENT REPORT OF:		
	TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	REPAIRING W	[]	
	SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZEN	ALTERING CA	SING	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any nent to this work.)*

Plugs set as follows on 7/25/78:

REPAIR WELL

(Other)

3600' 50 sx. 2500' 50 sx. 1250' 50 sx. Surface 10 sx.

CHANGE PLANS

18. I hereby certify that the foregoing is true *See Instructions on Rayesse Sid SIGNED 4 (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: DATE