N ), OF COPIES RECEIVED		Form C-103 Supersedes Old
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	
FILE	-	5a. Indicate Type of Lease
U.S.G.S.	4	State X Fee
LAND OFFICE		5. State Oil 6 Gas Lease No.
OPERATOR		B-10784
CONOT USE THIS FORM FOR PH	RY NOTICES AND REPORTS ON WELLS DIGSALS TO DALL OF TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOID. TICH FOR PLANIT - " (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
1. OIL X GAS WELL	0THER.	
write [X] write []	E. Farm or Lease Name	
	State EX	
Amoco Production Company	9. Well No.	
P.O. Drawer A, Levella	10. Field and Pool, or Wildcat	
4. Location of Well	Vacuum Grayburg San Andria	
UNIT LETTER	1768 FEET FROM THE NORTH LINE AND 990 FEET FROM	THUR THUR THUR STREET
l	10N TOWNSHIP 18-S RANGE 34-E NMEM	
THE WEST LINE, SECT	ION TOWNSHIP RANGE NMPM	XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
mmmmmm	12. County	
	Lea	
te. Check	Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
	INTENTION TO: SUBSEQUEN	T REPORT OF:
		ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	COMMENCE DE LLING DENS.	
PULL OR ALTER CASING	CHANCE PLANS CASING TEST AND CEMENT JOB	
	OT HER	L
OTHER		
	Charles all waterent details and sive pertinent dates, includin	e estimated date of sturting any proposed

17. Descrine Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to add additional cement behind 5 1/2" casing. 5 1/2" 14# K-55 ST&C casing was set at 4750', 5-12-78 and cemented with 300 sx Class "C" cement. Cement did not circulate and verified top of cement at 2995' by temperature survey. Propose to run retrievable BP and set at 3100' and cap w/ 10' sand and perforate 5 1/2" csg at 2950' w/4JSPF and establish circulation. Run tbg w/retainer and set 50-100 ft. above perfs. Cement w/700sx filler cement w/additives followed by 50sx Incor Neat. Circulate cement to surface. Pull tbg and drill out cement and retainers and return well to production.

15. Thereby certify that the information	on above as true and comp	TITLE	Administrative Supervisor	8-1-78
ATTHROVED BY	July Sign	TITLE		AUG 4 13/8