CHANGE ZONES ABANDON\*

(other) DST

UNITED STATES  DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	5. LEASE  NM-077002  6. IF INDIAN, ALLOTTLE OR TRIBE NAME	
SUPERTY NOTICES AND REPORTS CIT WELLS (Do not use this form for proposals to drill or to deepen or plug back to a difference reservoir, it e Form 9-501- C for each proposals.)	7. UNIT AGREEMENT NAME  8. FARM OR LEASE NAME	
1. oil gas [X] other	Nellis Federal  9. WELL NO.	
2. NAME OF OPERATOR Amoco Production Company	10. FIELD OR WILDOAT NAME	
3. ADDRESS OF OPERATOR P. O. Drawer "A", Levelland, TX 79336	Und. Buffalo Penn Morrow  11. SEC., T., R., M., OR BEK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 1 below.)	0-13-00	
AT SURFACE: 1980' FNL & 1980' FWL, Sec. 6 AT TOP PROD. INTERVAL: (Unit F, SE/4, NW/4)	12. COUNTY OR PARISH 13. STATE Lea New Mexico	
AT TOTAL DEPTH:  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	14. API NO.	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3699.7 GR	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE		
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Drilled to TD of 12,640' and ran DST #1 12,597-12,640' Atoka. DST results attached. Continued drilling to TD of 13,317' and ran DST #2 13,240-13,317' Morrow. DST results attached. Continued drilling.



U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO

Subsurface Safety Valve: Manu. and Type		Set @ Ft.
18. Thereby certify that the pregoing is	true and correct	
SIGNED Kay by	TITLE Admin. Supervisoroan	EApril_9, 1979
	(This space for Federal or State office use)	1000
APPROVED BY	TITLE	TE um PT Bad
0+4-USGS,H 1-Susp.		OF STATE OF
1-RWA 1-Hou	*See Instructions on Reverse Side	

COARTMAN SOLUTION

OIL CONTROLLS IN MA

À

Care Contract