			en e		
Form 3160-5 November 1983) Formerly 9-331) DEPARTMI		NITED STATES BUBMIT IN TRIPLICALE (Other Instructions on re-		Expires August 31, 1985 6. LEASE DESIGNATION AND SEREAL NO.	
	BUREAL	J OF LAND MANAGEMENT		NM-63026	
(De	SUNDRY NOTION OF THE POLICATION OF THE POLICATIO	CES AND REPORTS Of the to drill or to deepen or plug baction FOR PERMIT—" for such pro-	N WELLS to a different reservoir.	6. IF INDIAN, ALLOTTEE	OR TRIBE HAME
I. OIL GAB OTHER				7. UNIT AGREEMENT NAME	
2. HAME OF OPERATOR				8, PARM OR LEASE WAME	
Manzano Oil Corporation 505/623-1996				Federal 7 Com	
3. ADDRESS OF OFERATOR				#n /	
P.O. Box 571/Roswell, NM 88202 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*				10. FIELD AND POOL, OR WILDCAY	
See also space 17 below.) At surface				Undesignated Bone Spring	
1980' FNL & 660' FWL				11. BRC. T. R. M. OR BLK. AND SURVEY OR ARRA 7 19S 33E	
14. PERMIT		1 15. BLEVATIONS (Show whether by, 9	IT, OR, etc.)	12. COUNTY OR PARISH	18. STATE
		3659.4' GR		Lea	NM
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO:					
TEST WATER SHUT-OFF PULL OR ALTER CABING WATER SHUT-OFF				ESPAIRING V	
PRACTURE TREAT MULTIPLE COMPLETE PRACTURE TREATMENT			-	ALTERING CA	
BROOT OR ACIDIES ABANDON* BROOTING OR ACIDIEING (Other)			_i .	·	
			(Nors: Report results	of maltiple completion	on Well
(Other) Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED ON COMPLETED OPERATIONS (Clearly state all pertisent details, and give pertinent dates, including estimated date of starting any					
17. DESCRIBE PROPOSED OF COMPLETED OPERATIONS (Clearly state all perturbat seculous and measured and true vertical depths for all markers and sones pertinent to this work.)*					
2/27/87	Moved in and rigo	ged up well service &	reverse unit. Dril	led surface plu	ia 2nd nlua
thru					
3/3/87					
3/4/87	Milled over $5\frac{1}{2}$ " casing cut off @ 5210 w/7-3/4" mill, milled 2' to 5212'. Ran 31 jts				
	J55 17# LT&C 8 rd casing (1,2221.17'), 29 jts J55 $5\frac{1}{2}$ " 15.5# ST&C 8 rd (1,198.44') and 72 jts J55 $5\frac{1}{2}$ " 17# ST&C 8 rd (2,786.99') plus extension 4.55' = 7" welded on cso Total footage ran 5,211.15'. Got over $5\frac{1}{2}$ " cut off w/8' 7" extension, cut off csg. Installed production head & picked up 4-3/4" bit, 6-3-1/8" collars & went in hole to cut off. Got inside $5\frac{1}{2}$ " casing & drld cmt @ 5212, fell thru @ 5277'. Tagged				
3/5/87	next plug @ 7446, drld to 7571. Circulated clean.				
3/3/0/	/87 Drld cmt @ 7571, fell thru @ 7620', circ clean. Pulled out of Hole & rigged up Halliburton. Cement 5½" casing w/175 sks Class C w/2% CaCl. Plug down @				
1:00 p.m. 3/4/87.					
3/6/87			le & tagged top of c	mt @ 5003'. fel	l out @ 5220'.
, -,	WOC 19½ hrs. Ran bit & collars in hole & tagged top of cmt @ 5003', fell out @ 5220'. Tested casing to 1500#, held OK. Ran tbg, tagged CIBP @ 10,655'. Prep to drill				
	out CIBP.	•			•

San Instructions on Rosson Ode

CARLSBAD, NEW MEXICO