

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ARTASIA	
FILE	
5.6.5.	
AND OFFICE	
PERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT WITH FORM C-101 FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>1. State Oil & Gas Lease No. L-6940</p>		
<p>2. Unit Agreement Name</p>		
<p>3. Form or Lease Name Reeves KK State</p>		
<p>4. Well No. 1 1</p>		
<p>5. Field and Pool, or Wildcat Reeves Penn.</p>		
<p>6. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>14</u> TOWNSHIP <u>18S</u> RANGE <u>35E</u> NMPLA.</p>		
<p>7. Elevation (Show whether DF, RT, GR, etc.) 3896.6' GR</p>		<p>12. County Lea</p>

<p>Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>			
<p>NOTICE OF INTENTION TO:</p>		<p>SUBSEQUENT REPORT OF:</p>	
<p>PERFORM REMEDIAL WORK <input type="checkbox"/></p>	<p>PLUG AND ABANDON <input checked="" type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p>
<p>TEMPORARILY ABANDON <input type="checkbox"/></p>	<p>CHANGE PLANS <input type="checkbox"/></p>	<p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p>	<p>PLUG AND ABANDONMENT <input type="checkbox"/></p>
<p>PULL OR ALTER CASING <input type="checkbox"/></p>	<p>OTHER <input type="checkbox"/></p>	<p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p>	<p>OTHER <input type="checkbox"/></p>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

TD 11500'; PBTD 4570'. Approval was given by the NMOCDC at Hobbs, New Mexico to plug well as follows: Displaced hole w/mud, pulled tubing and packer out of hole. RIH w/tubing and spotted 50 sacks of Class C plug at 4460', pulled tubing up to 1657' and pumped 10 bbls gelled water and mud ahead of 25 sacks of Class C cement. Pulled tubing out of hole, removed BOP and loaded hole w/ 6 bbls gelled water and mud, spotted 5 sacks of Class C plug to surface w/dry hole marker. P & A 9-19-79.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

<p>SIGNED <u>Christine L. Sullivan</u></p>	<p>TITLE <u>Geol. Secty.</u></p>	<p>DATE <u>9-22-79</u></p>
<p>SIGNED <u>Jerry Sexton</u></p>	<p>TITLE <u>Dist. L. Supp.</u></p>	<p>DATE <u>SEP 26 1979</u></p>