

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-26223
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2229
7. Lease Name or Unit Agreement Name: Philmax
8. Well No. 13
9. Pool name or Wildcat Maljamar / Grayburg - San Andres
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4145' GL / 4161' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	4. Well Location Unit Letter B : 330 feet from the North line and 1980 feet from the East line Section 27 Township 17-S Range 33-E NMPM County Lea
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

03/17/02 MIRU BASIC ENERGY SERVICES P & A PACKAGE #2282. OBJECTIVE: P & A PHILMAX #13. LOCATED: UNIT B, 330' FNL & 1980' FEL, SEC 27, T-17-S, R-33-E, LEA COUNTY, NEW MEXICO. NOTIFIED NMCD'S SYLVIA DICKIE (15:25 P.M. 03/14/02) OF INTENT TO COMMENCE P & A OPERATIONS. DIG TESS #2002072007. ND WH, NU CLASS 1 BOPE. PU WS, GIH TAG CIRP @ 4340'. CIRC 9.5# MLF (MUD LADEN FLUID). * NOTE: ALL PLUGS CLASS "C" CEMENT, 14.8#, 1.32 YD. PUMP PLUG #1 (50 SX, INTERVAL 4340'-3584', DISPLACE W/ 13.5 BBL MLF). POOH, LD WS TO 2900'. SECURE WELL. SDON.

** CONTINUED ON BACK **

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stacy L. Sanders TITLE Supervisor, Reg./ Pro. DATE 04/01/02
Type or print name L. M. Sanders Telephone No. 915/368-1488

(This space for State use)
APPROVED BY Johnny Robinson TITLE CLERK OF COURSE OFFICER DATE NOV - 1 2002
Conditions of approval, if any: GW

Continued:

PHILMEX #33

03/18/02 TRAVEL TO LOCATION. PUMP PLUG #2 (25 SX, INTERVAL 2900'-2522', DISPLACE W/ 9.5 BBL MLF). POOH, LD WS TO 1650'. PUMP PLUG #3 (25 SX, INTERVAL 1650'-1272', DISPLACE W/ 4.5 BBL MLF). POOH. WOC. GIH, TAG PLUG #3 @ 1300'. POOH, LD WS TO 500'. PUMP PLUG #4 (35 SX, INTERVAL 500'-SURFACE). POOH, LD WS. CLEAN OUT AND NIPPLE DOWN BOPE. RDMO, BASIC ENERGY SERVICES P & A PACKAGE #2282. PERFORM RECLAMATION WORK, INSTALL DRY HOLE MARKER. P & A OPERATIONS COMPLETE.

MATERIAL TRANSFER:

#799491 -

WELLHEAD EQUIP.