

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-26423
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2148
7. Lease Name or Unit Agreement Name: LEAMEX
8. Well No. 23
9. Pool name or Wildcat MALJAMAR GB/SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	4. Well Location Unit Letter F : 1980 feet from the NORTH line and 1980 feet from the WEST line Section 24 Township 17-S Range 33-E NMPM LEA County
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4125.5' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ADD GRAYBURG PERFS, ACIDIZE, REACTIVATE ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

06/01/01 MIRU POOL #587
06/04/01 NU BOP PU BIT DC'S TBG GIH TAG CIBP 4355' DU PLUG & CLEAN T/4560' WASH & PULL UP.
06/05/01 DO T/4630' CIRC T/CLN UP COOH LD DC'S TRIP CSG SCRAPER T/4579' RUN KS.
06/06/01 PULL KS MIRU JARREL WL PERF GRAYBURG-SA 4362-4364, 4366-4375, 4421-4422, 4435-4436, 4451-4452, 4487-4488, 4490-4491, 4513-4517, 4567-4569' 2 SPF 44 HOLES RD JSI GIH W/PKR & SET 4295' MIRU PMP TRK PMP 10 BBL EXYLENE FOLLOW BY 18 BBL WTR TP 1400 PSI SI LD BK SIDE W/FW.
06/07/01 MIRU HES ACIDIZE GRAYBURG PERFS 4362-4569' 5000 GAL 15% NEFE 900# RKSALT IN GELL BRINE HI PRESS THRUOUT TK 6 BBL T/LD TBG PRESS 1280 PSI END FLUSH PRESS 2614 PSI ISIP 2285 5 MIN 1824 10 MIN 1704 15 MIN 1616 MAX PRESS 2614 AVG 2293 MAX PMP RATE 4.0 BPM LD 163 BBL SI RD HES OPEN UP T/FRAC TK BLOW BK 17 BW RU SWAB START LEV 2200 F/SURF PULL F/SEAT NIP GET 500-600' FL 1 HR FLOW/SWAB TOT 75 BW.

CONTINUED ON BACK

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE SUPV., REGULATION/PRORATION DATE 6/20/01
Type or print name L. M. SANDERS Telephone No. 915-368-1488

(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:

LEAMEX #23

06/08/01 CONTINUED

SWAB REPT: TP SLIGHT BLOW FL 3000' F/SURF SWAB BK 18 BBL TOT 6 BO 12 BW PULL
F/SEAT NIP GET 500-600' ENTRY 1 HR.

06/11/01 TP 100 PSI BLD OFF TP SWAB FL 3000' F/SURF SWAB BK 10 BBL TOT 20% OIL CUT ON
SAMPLE SWAB DWN T/SEAT NIP, REL PKR COOH LD WS UNLD 2-3/8 J55 TBG PU GIH W/TBG
RAN 135 JTS 2-3/8 J55 8RD TAC @ 4236' RAN 10 JTS 2-3/8 SEAT NIP (EOT) @ 4550'.

06/12/01 ND BOP PU NEW PMP NEW ROD STG RUN RODS BLD NEW WH ASSY LD TST TBG SPACE OUT
PMP HANG ON PMP T/LEAMEX 8 BATT TST T/FOLLOW RD POOL DDU TEMP DROP F/REPORT.

06/15/01 24 HR TST: 0 BO 9 BW 2 MCF GAS

06/16/01 24 HR TST: 0 BO 6 BW 2 MCF GAS

06/17/01 24 HR TST: 0 BO 6 BW 2 MCF GAS - DROP F/REPORT - JOB COMPLETE

