

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-2229

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	SMGSAU
3. Address of Operator	8. Farm or Lease Name
Box 1919 Midland, TX 79702	Tract 5
4. Location of Well	9. Well No.
UNIT LETTER G, 2615 FEET FROM THE North LINE AND 2615 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 17S RANGE 33E NMPM.	10. Field and Pool, or Wildcat
	Maljamar G-SA
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4069.8' GR	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 4380'. Dolomite

Ran 17 joints (673.15') of 4" OD 11.34# N80 Hydril SFJ liner set at 3696' - 4379' & cmted w/50 sx Class C w/0.3% CFR-2 & 5# salt/sx. PD @ 1745 MST 1/21/80. Did not reverse out. WOC 12 hrs. RIH w/4-3/4 RB & 4 3 1/2" DC's on 2-3/8 EUE tbq. Tagged @ 3451'. Press tested 5 1/2 csg to 1000# ok. Prepare to drill out cmt.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jerry Sexton</u>	TITLE <u>Region Oper. Mgr.</u>	DATE <u>2/8/80</u>
APPROVED BY <u>Jerry Sexton</u>	TITLE <u>Dist. 1. Supv.</u>	DATE <u>FEB 11 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		