

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division  
P.O. Box 1900  
Hobbs, NM 88240

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Nearburg Producing Company

3. Address and Telephone No.

P. O. Box 823085, Dallas, TX 75382-3085 (214) 739-1778

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2,180' FSL & 660' FEL, Sec. 1, T-19-S, R-33-E

5. Lease Designation and Serial No.

NM-4312

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Pennzoil Federal #1

9. API Well No.

30-025-26498

10. Field and Pool, or Exploratory Area

"EK" Bone Spring

11. County or Parish, State

Lea County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☒ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. MIRU. 1-13-97.
2. POH with completion setting.
3. Run CBL f/10,450' - 9,000'. TOC at + 9,554'.
4. Set CIBP at 9,645' and cap with 35' cement. New PDTD at 9,610'.
5. Perforate Bone Spring 9,300' - 78' with casing gun at 2-JSPF.
6. Acidize and test.
7. Swab Bone Spring.
8. Put on production 2-6-97.
9. RDMO

RECEIVED  
1997 MAY 16 P 9 54  
BUREAU OF LAND MGMT.  
ROSSELL OFFICE

14. I hereby certify that the foregoing is true and correct

Signed

Title Mgr. of Drilg and Prod.

Date 5/14/97

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

2A N Quail Ridge dp  
Morrison