

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other

2. NAME OF OPERATOR

Chama Petroleum Company

3. ADDRESS OF OPERATOR

P.O. Box 31405, Dallas, Texas 75231

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 2180' FSL & 660' FEL Sec. 1

AT TOP PROD. INTERVAL: Same

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Recomplete

5. LEASE

NM-4312

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Pennzoil Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME Undesignated
North Quail Ridge (Morrow)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 1, 19S, 33E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3776.0' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-29-83: Rigged up Ryco Wireline, ran gauge ring & junk basket to 13,290', ran Halliburton SB cement retainer on wireline, tied into PDC log, set retainer at 13,188', started out of hole with setting tool, PTO came out of gear, operator set break on drum & wireline parted leaving approx. 10,800' of wireline in hole, waited on another wireline unit & fishing tools, rigged up another wireline truck, tripped in hole with wireline spear & jars, tagged wireline fish at 3,053', pulling wireline & tools out of hole & started dragging, pulled out of rope socket leaving wireline & fishing tools in hole, rigged down wireline, waited on fishing tools to fit tubing, tripped in hole with 3 prong grab on 2 3/8" tubing, tagged fish at 3,450', set down several times with grab, torque up on grab, picked up & bent at 1500# pull over weight, lost pull on 1st stand, retagged fish & lost pull again, pulled out of hole, grab was bent in & metal to metal mark, wireline fishing tools still on top of line, closed in overnight.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Nathie Craft TITLE Prod. Secretary DATE August 15, 1983

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: