Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 WELL API NO. P.O. Box 2088 30-025-26587 DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Anesia, NM 88210 5. Indicate Type of Lease STATE 1000 Rio Brazos Rd., Aztec. NM 87410 6. State Oil & Gas Lease No. C-786 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: Gulf State WELL X OTHER Name of Operator 8. Well No. Mineral Technologies, Inc. Address of Operator 9. Pool name or Wildcat P.O. Box 5823; Midland, TX 79704 Buckeye ABO Well Location 1980 Feet From The Unit Letter _ North 660 West Line and Feet From The Line Section 18-S 35-E Township Lea Range **NMPM** County 10. Elevation Show whether DF, RKB, RT, GR, etc., Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OF ALTER CASING CASING TEST AND CEMENT JOB : OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent setails, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 01-22-98 - Notified OCD. MIRU. POOH w/ tbg. 01-23-98 - POOH w/ remaining tbg. RIH to 6803', loaded hole and pumped 25 sx C cmt. Tagged plug @ 6453'. Circulated hole w/ mud. 01-26-98 - Contacted Chris w/ OCD. Stretched 4-1/2" csg, freepoint @ 1543' to 1703'. Contacted Chris. Will perf csg @ 3606' as directed. RIH and set packer, established rate and squeezed 45 sx C cmt w/ CaCl,. Tagged plug @ 3471'. Cut 4-1/2" csg @ 1672'; POOH w/ 4-1/2" csg. RIH w/ tbg and pumped 45 sx C cmt w/ CaCl₂, Will tag plug on 1-27-98. 01-27-98 - Tagged plug @ 1547'. Pumped 35 sx C cmt @ 1207'. WOC and tagged plug @ 1092'. Pumped 35 sx C cmt 352-210'. Pumped 10 sx C cmt 30'-surface, RDMO. 02-5-98 - Cut off wellhead, capped well, installed dry hole marker. Perations Superuntendent 2-6-98 SIGNATURE J.L.Grégg 915-620-6032 TYPE OR PRINT NAME

Thus space for State Use y Robinso

5 >> ==

TELEPHONE NO.

CONDITIONS OF