

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE	
FILE	
U.S. G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

State ☒	Fee ☐
State Oil & Gas Lease No. E-7723	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - FORM C-1011 FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Energy Reserves Group, Inc.	8. Form or Lease Name T P State
3. Address of Operator P. O. Drawer 2437, Midland, Texas 79702	9. Well No. 2-Y
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1880 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 18-S RANGE 35-E MAP	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3950 GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 08-19-81 TD 9156' PBDT 8920'. MIRU PU. Pulled 7 jts. 2 3/8" tbg. Displaced hole w/fresh water mud. Spot 200' cmt. plug @ 8668'. TOH w/2 3/8" tbg. Remove wellhead. Cut off 4 1/2" csg. @ 5770' & pulled free.
- 08-20-81 TD 9156'. Pull & LD 148 jts. (5771.53') 4 1/2" csg. TIH w/2 7/8" tbg. Load hole w/10# brine. Spot 25 sax. plug 5720'-5820'. Pull 12 std. tbg. & SD.
- 08-21-81 TD 9156'. Well P&A. Tag top cmt. plug @ 5721'. Spot 6 cmt. plugs as follows:
 #1 - 8468'-8668' w/25 sax. Class "H"
 #2 - 5720'-5820' w/25 sax. Class "H"
 #3 - 5120'-5220' w/35 sax. Class "H"
 #4 - 3553'-3653' w/35 sax. Class "H"
 #5 - 1800'-1700' w/35 sax. Class "H"
 #6 - Surface w/10 sax. Class "H"
 Weld on steel plate & install dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. L. Robertson TITLE Production Engineer II DATE 09-09-81
 APPROVED BY Eddie W. Seay TITLE OIL & GAS INSPECTOR DATE APR 28 1982
 CONDITIONS OF APPROVAL, IF ANY: