N . OF COPIES RECEIVED				Supersedes Old		
DISTRIBUTION				C-102 and C-10	₹	
ANTA FE	NEW ME	EXICO OIL CONSE	ERVATION COMMISSION	Effective 1-1-65		
ILE				Sa. Indicate Type o	i Lease	
AND OFFICE	+	CORRECTED*			Fco 🗌	
PERATOR			5, State Oil & Gas LG 342!			
SU	INDRY NOTICES AND	REPORTS ON	WELLS			
	CLICATION FOR PERMIT! (F	ORM C-101) FOR SUCH	CK TO A DIFFERENT RESERVOIR.	7. Unit Agreement	Name	
OIL X GAS WELL . Name of Sperator	OTHER-			8. Farm or Lease 1		
Coquina Oil Corporation					State 747	
P. O. Drawer 2960, Midland, Texas 79702				1		
Location of Well A 330 FEET FROM THE North LINE AND 330 FEET FROM				10. Field and Fool	•	
5.11. EE. 1.11. <u></u>	•	•		FROM THITTING		
THE East LINE,	SECTION35	TOWNSHIP 18-5	RANGE 34-EN	EMPAC ()		
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	ntion (Show whether 1972 GR	DF, RT, GR, etc.)	12. County Lea		
Ch			ature of Notice, Report of		***********	
	OF INTENTION TO:			JENT REPORT OF:		
PERFORM REMEDIAL WORK	PLU	G AND ABANDON	REMEDIAL WORK	₹	NG CASING	
TEMPORARILY ABANDON		r 	COMMENCE DRILLING OPNS.	PLUG AN	ID ABANDONMENT	
PULL OR ALTER CASING	C HA	NGE PLANS	CASING TEST AND CEMENT JOB	rface casing		
OTHER						
17. Describe Proposed or Comple	eted Operations (Clearly st	ate all pertinent deta	ails, and give pertinent dates, incl	luding estimated date of s	tarting any proposed	
work) SEE RULE 1103.	·no p M .lune 4	1980 Dril	lled 17 1/2" hole to	331' with spud	mud.	
_			nd set at 330.64'. C			
Class C w/2% calciu	um chloride and ⁻	1/4# flocele	per sack. Tested to	COO : 11-1 J		
) 600 psi. нета	0K.	
Plug down at 9:28 A			ted 75 sacks to surfa		•	
•	A.M., June 5, 198	30. Circulat		ice. WOC 18 hrs	•	
•	A.M., June 5, 198	30. Circulat	ted 75 sacks to surfa	ice. WOC 18 hrs	•	
•	A.M., June 5, 198	30. Circulat	ted 75 sacks to surfa	ice. WOC 18 hrs	•	
-	A.M., June 5, 198	30. Circulat	ted 75 sacks to surfa	ice. WOC 18 hrs	•	
•	A.M., June 5, 198	30. Circulat	ted 75 sacks to surfa	ice. WOC 18 hrs	•	
BOP's and picked up	A.M., June 5, 198	30. Circulat sembly. Prep	ted 75 sacks to surfa	ace. WOC 18 hrs whead.	•	
BOP's and picked up	A.M., June 5, 198 p bottom hole ass	30. Circulat sembly. Prep	ted 75 sacks to surfact to start drilling a	ace. WOC 18 hrs whead.	•	
BOP's and picked up	A.M., June 5, 198 p bottom hole ass	So. Circulate sembly. Prepty typographical complete to the best	ted 75 sacks to surfact to start drilling a	ice. WOC 18 hrs	•	
*Corrected report	A.M., June 5, 198 p bottom hole ass	So. Circulate sembly. Prepty typographical complete to the best	ted 75 sacks to surfact to start drilling a all error from 500 psi	ice. WOC 18 hrs	. NU	