

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: <u>INJECTOR</u>	7. Unit Agreement Name <u>N. HOBBS (G/SA) UNIT</u>
2. Name of Operator <u>SHELL OIL COMPANY</u>	8. Farm or Lease Name <u>SECTION 30</u>
3. Address of Operator <u>P. O. BOX 991, HOUSTON, TX 77001</u>	9. Well No. <u>222</u>
4. Location of Well UNIT LETTER <u>F</u> <u>1470</u> FEET FROM THE <u>NORTH</u> LINE AND <u>1395</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>30</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat <u>HOBBS (G/SA)</u>
11. Elevation (Show whether DF, RT, GR, etc.) <u>3654.23' GR</u>	12. County <u>LEA</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/29-30/80: Perf'd 5 1/2" csg 4322' - 4329'. Set pkr @4316' and spot 50 gals 15% HCl NEA acid on btm.

8-5-80: Acidized perfs 4322' - 4329' w/500 gals NCl NEA acid.

8-19-80: Started well to pumping.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REGULATORY & PERM. DATE JULY 6, 1981

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: