

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-26852
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2148
7. Lease Name or Unit Agreement Name: LEAMEX
8. Well No. 29
9. Pool name or Wildcat MALJAMAR GRAYBURG/SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	
4. Well Location Unit Letter <u>L</u> : <u>1980</u> feet from the <u>SOUTH</u> line and <u>660</u> feet from the <u>WEST</u> line Section <u>24</u> Township <u>17S</u> Range <u>33E</u> NMPM County <u>LEA</u>	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4125' RKB, 4115' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CO & STIMULATE PERFS ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

05/04/01 MIRU POOL #682 COOH W/ROD STGS PMP NU BOP COOH W/PROD TBG TRIP SND PMP TAG FILL @ 4616' RUN KS
05/07/01 TRIP 4-1/2 CSG SCRAPER T/4586' MIRU HES PERF GRAYBURG 2 SPF FIRE 20 HOLES 4332-4336,
4340-4341, 4472-4474, 4489-4490, 4501-4502, 4570-4571 RD HES W/ TBG TSTRS PU 4-1/2 PKR
& TST TBG SET PKR @ 4290' LD BKSIDE W/FW.
05/08/01 MIRU HES TST LNS ACIDIZE GRAYBURG 4332-4571' W/4000 GAL 15% HCL ACID 800# RKSALT & 800 GAL
GELBRINE GOOD BLOCK ACTN STGS 1 & 2 PRESS UP T/2533 PSI STG 1 & 1610 STG 2 BOTH FORM PRESS
BROKE BK SOON AFTER ACID ON MAX PRESS 2533 AVG 812 ISIP 997 5 MIN 312 10 MIN 14 5 MIN ON VAC
TOT LD 131 BBL SI RD HES RU SWAB FL 1500' F/SURF LEVEL DROP EA 5 RUNS SWAB F/SEAT NIP RUN EA
HR LIMITED FL ENTRY SWAB BK 28 BBL TOT WATER.

(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry M. Sanders TITLE SUPERVISOR, REG./PRORATION DATE 5/17/01
Type or print name LARRY M. SANDERS Telephone No. 915/368-1488

(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:

LEAMEX #29 CONTINUED

05/09/01 TP 90 CP 0 PSI FL 4000' F/SURF 1ST RUN SWAB BK 200' FL PULL F/SEAT NIP 60% OIL CUT
SWAB DRY MKNG HRLY RUN VERY LITTLE FL ENTRY SWAB BK 5 BBL TOT RD SWAB REL PKR
COOH W/TBG PU NEW SEAT NIP GIH RAN 148 JTS 2-3/8 TBG SEAT NIP @ 4569' TAC 4319' ND
BOP NU WH ASSY.

05/10/01 RUN NEW PMP ROD STG LD TBG CK PMP ACTN HANG ON PMP T/LEAMEX BATT WILL BE PUT
ON TST AS SCHEDULE ALLOWS RD POOL DDU.

05/11/01 PUT ON TST THRU TST HEATER @ LEAMEX 8 BATTERY.

05/12/01 24 HR TST: 0 BO 10.1 BW 6.1 MCF GAS - GAS LOCKED.

05/13/01 NO TST - GAS LOCKED.

05/14/01 24 HR TST 2 BO 2 BW 2 MCF GAS

05/15/01 24 HR TST 2 BO 3 BW 4 MCF GAS

05/16/01 24 HR TST 0 BO 4 BW 13.8 MCF GAS - COMPLETE DROP F/REPORT

