Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office				
DISTRICT I	OIL CONSERVATIO		WELL API NO.	
P.O. Box 1980, Hobbs NM 88240 DISTRICT II	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-025-26929	
P.O. Drawer DD, Artesia, NM 88210	Salita Pe, New Mexico	0 87304-2088	5. Indicate Type of Lease STATE X FEE	$_{\square}$
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	_
SUNDRY NOT	TICES AND REPORTS ON WEL	18	B-1502 	7777
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
	:RVOIR. USE "APPLICATION FOR PER :-101) FOR SUCH PROPOSALS.)	MIT"	7. Lease Name or Unit Agreement Name	
1. Type of Well:	- 101) FOR SUCH PROPUSALS.		EAST VACUUM GB/SA UNIT	
OIL GAS WELL WELL	OTHER		TRACT 0524	
2. Name of Operator			8. Well No. 002	
Phillips Petroleum Com 3. Address of Operator	Jany		9. Pool name or Wildcat	-
4001 Penbrook Street, (Odessa, TX 79762		VACUUM GB/SA	
4. Well Location Unit Letter C 95	O Feet From The NORTH	Line and13	50 Feet From The WEST	Line
Section 5	Township 18–S Ra	ange 35-E	NMPM LEA Co	ounty
	10. Elevation (Show wheth	er DF, RKB, RT, GR, et 3962'GR	c.)	
11. Check A 1	WWW.		Parant on Other Date	
•	ppropriate Box to Indicate NTENTION TO:	1	• ′	
NOTICE OF I	NIENTION IO:	306	SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMEN	п 🗆
PULL OR ALTER CASING		CASING TEST AND CE	EMENT JOB	
OTHER: ADD PERFS, ACIDIZE	RETURN TO PROD	OTHER:		⊏
12. Describe Proposed or Completed On	erations (Clearly state all pertinent det	ails, and give pertinent da	tes, including estimated date of starting any pro	nosed
work) SEE RULE 1103.	(, g p p	,,	Postu
1. MIRU DDU. KILL WELI	. PULL RODS & PUMP. NU	BOPE, COOH W/T	BG, RIH W/SAND PUMP OR SCRAI	PER.
CLEAN OUT TO 4706.	, , , , , , , , , , , , , , , , , , , ,		,,	,
			78'-4386', POOH, RD HLS.	
			CALCIUM SULFATÉ IS FOUND, ET 425, 5 DRUMS TECHNI-CLEAI	N 405
IN 275 GALS WATER.				
4. RU SWAB, SWAB CHEME 5. RIRU HLS. ACIDIZE S		4500 GALS FERCH	ECK 15% ACID, RDMO HLS, RU S	SWAB.
SWAB BACK LOAD.	·		•	•
			RDMO HLS, RU SWAB, SWAB BAC	Ж,
8. TEST, REPORT TEST.	RODS & TBG AS BEFORE, I	RETURN WELL TO	PRODUCTION.	
o. ILSI, KEFOKI ILSI.				
I hereby certify that the information above is	true and complete to the best of my knowledg	e and belief.		
SIGNATURE	anders III	LE REGULATION SE	PECIALIST DATE 6/02/95	
TYPE OR PRINT NAMEMSANDE	RS		TELEPHONE NO.915/368-	<u>1488</u>
(This space for State Use)	MAL GIGNED BY			
- :	MARY WINK		JUN 14 19	Q5
APPROVED BY	ELD REP. II	LE	DATE	

RECEIVED

OFFICE
OFFICE