STATE OF NE. MEXICO ENERGY AND MINERAL'S DEPARTMENT

71131 2113 111121112 0		
MB BF COPIES RECE :		
DISTRIBUTIC		
BANTA FE		
FILE		İ
U.S.G.S.		
LAND OF FICE		
OPERATOR	1	ĺ

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 Revised 10-1-78

SANTA FE, NEW MEXICO 87501	
FILE	5a. Indicate Type of Lease
U.S.G.S.	State X Fee
LAND OFFICE	5. State Oli 6 Gas Lease No.
OPERATOR	
	mmmmm
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DELPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
	7. Unit Agreement Name
OIL GAS	WORDS (C/CA) UNITE
WELL WELL OTHER INJECTOR	N. HOBBS (G/SA) UNIT
2. Name of Operator	o. Famer Bedde Fame
SHELL OIL COMPANY	SECTION 32
3. Address of Operator	9. Well No.
	432
P. O. BOX 991, HOUSTON, TX 77001	10. Field and Pool, or Wildcat
4. Location of Well	1
UNIT LETTER I , 1400 FEET FROM THE SOUTH LINE AND 1300 FEET FROM	HOBBS (G/SA)
UNIT CELLULA	
THE EAST LINE, SECTION 32 TOWNSHIP 18S RANGE 38E NMPN	
THE FADT LINE, SECTION 32 TOWNSHIP TOO RANGE 302 HADE	Allillillillilli
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3629.3' GR	LEA (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Check Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
	T REPORT OF:
NOTICE OF INTENTION TO: SUBSEQUEN	TREFORT OF.
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
CARING TEST AND CEMENT JOB	
OTHER COMPLETE AS AN S	SA II. IIIu INJECTOR X
C)	
OTHER	
and the second s	a estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	, , , , , , , , , , , , , , , , , , , ,
work) SEE RULE 1103.	
6-17-81: Co to 4265'. Spot 250 gals 15% HCl double inhibited acid.	
6-17-61. Co to 4203. Spot 230 gate 13% not declare	
100 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- @30631
6-18-81: Perf'd 5 1/2" csg 4062' - 4250'. Set top pkr @3945', btm pkr	. 63703 .
Pressure test between pkrs and plank pipe to 1100 psi - held	OK.
Acidized perfs w/6100 gals 15% HCl NEA inhibited acid.	
6-20-81: Set pkr @3941' w/12,000# tension. Well Complete.	
6-20-81: Set pkr @3941' w/12,000# tension. Well Complete.	
•	
\cdot	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
110 true	DATE JUNE 30, 1981
SICHED TITLE	
nay plant of	•
execution of the second of	JUL 6 1981
lean and the second of the sec	UUL V 1991