

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0115
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ INJECTOR	7. UNIT AGREEMENT NAME N. HOBBS (G/SA) UNIT
2. NAME OF OPERATOR SHELL WESTERN EBP INC.	8. LEASE OR AGREEMENT NAME SECTION 30
3. ADDRESS OF OPERATOR P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. WELL NO. 442
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1300' FSL & 1050' FEL SECTION 30	10. FIELD AND POOL, OR WILDCAT HOBBS (G/SA)
11. ELEVATIONS (Show whether of, to, or from) 3645.85' GR	11. SEC. T. R. S. OR BLM. AND SURVEY OR AREA SEC. 30, T18S, R38E
12. COUNTY OR PARISH LEA	13. STATE NM

15. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☒
FRACURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACURE TREATMENT ☐	ALTERING CASING ☐
SHUT-IN OR ACIDIZING ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANE ☐	(Other) ☐	

17. SUMMARY OF PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4-21-86: Pulled injection equipment.

4-22-86: Set RBP @ 4105' & pkr @ 3998'. Pmpd into zone 4065' - 4095' w/50 BPW. Did not catch pres. POH w/RBP & pkr. Set CIBP @ 4150' & CICR @ 3933'. Sqzd thief zone 4065' - 4095' (NOTE: Step 5 on Form 3160-5 dtd 3-25-86 incorrectly indicates perfs to be sqzd as 4070' - 4090' which to this date have not been opened) w/150 sx CIs "C" cmt + .2% Halad-4 + 2% CaCl₂ followed by 25 sx CIs "C" cmt + 2% CaCl₂.

4-23 to 4-25-86: Tagged TOC @ 3925'. Drld out cmt (& CICR @ 3933') to 4100'. Pres tstd sqzd zone 4065' - 4095' to 1000#, held OK 10 min. Re-pres tstd zone 4065' - 4095' & previously sqzd perfs 4110' - 4134' to 1000#, held OK 10 min. Drld out CIBP @ 4150' & pushed to btm (4462').

4-28 to 4-29-86: Installed injection equipment, setting Guiberson Uni-Pkr VI @ 3994'. Pres tstd csg & pkr to 500# for 20 min, held OK. Returned well to injection.

18. I hereby certify that the foregoing is true and correct

SIGNED A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE JULY 17, 1986

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY: _____

TITLE _____

ACCEPTED FOR RECORD

DATE RO

JUL 23 1986

*See Instructions on Reverse Side

CARISBAD, NEW MEXICO