

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name N.HOBBS (G/S) UNIT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name SECTION 19
3. Address of Operator P. O. BOX 991, HOUSTON, TX 77001	9. Well No. 142
4. Location of Well UNIT LETTER <u>M</u> <u>1200</u> FEET FROM THE <u>south</u> LINE AND <u>1300</u> FEET FROM THE <u>west</u> LINE, SECTION <u>19</u> TOWNSHIP <u>18S</u> RANGE <u>38E</u> N.M.P.M.	10. Field and Pool, or Wildcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3659.9' GR	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <u>8 5/8" csg.</u> <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-15-80: Ran 41 jts 8 5/8" 24# K55 ST&C csg. Set @1600' w/625 sx Howco Lite w/2% CaCl2 + 1/4# flocele, followed by 250 sx Class C w/2% CaCl2. Circ 16 bbls cmt to surface. Bump plug @3:10 pm. 16 hrs WOC.

12-16-80: 1/2 hr test pipe rams - 1500 psi.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A. J. Fore</u>	A. J. FORE	TITLE SUPERVISOR-REGULATORY & PERMITTING	DATE <u>DEC 22 1980</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>DEC 22 1980</u>	
CONDITIONS OF APPROVAL, IF ANY:			