

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-121) FOR SUCH PROPOSALS.)

CIL WELL ☐	CAB WELL ☐	OTHER- INJECTOR	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
Name of Operator SHELL WESTERN E&P INC.			8. Form or Lease Name SECTION 32
Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001			9. Well No. 222
Location of Well UNIT LETTER F 1720 FEET FROM THE NORTH LINE AND 1370 FEET FROM THE WEST LINE, SECTION 32 TOWNSHIP 18-S RANGE 38-E NMPM.			10. Field and Pool, or Widened HOBBS (G/SA)
11. Elevation (Show whether DF, RT, GR, etc.) 3634.55' GL			12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER SQUEEZE & ACIDIZE ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

1. Pull injection equipment.
2. Clean out to $\pm 4250'$.
3. Set CICR @ 4235'.
4. Squeeze San Andres perf's 4246' - 4258' w/50 sx Class "C" cmt leaving 5' - 6' cmt on top of CICR. WOC 24 hrs.
5. Acidize San Andres perf's 4090' - 4218' w/2500 gals of 15% HCl-NEA.
6. Install injection equipment (setting pkr @ 4015') and resume injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

A. J. Fore
A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JUNE 24, 1985
JUL - 1 1985