

- D. The reserve pit will be fenced on three sides throughout drilling operations. After the rotary rig is removed, the reserve pit will be fenced on the fourth side to preclude endangering wildlife. The fencing will be in place until the pit is reclaimed.
- E. If the well is deemed commercially productive, the reserve pit will be restored as described on 10 (A) within 120 days subsequent to the completion date. Caliche from the area of the pad site not required for operations will be reclaimed. The unused areas of the drill pad will be contoured, as close as possible, to match the original topography.

10. Surface Ownership:

The Well site is owned by the Bureau of Land Management.

Road routes have been approved and the surface location will be restored as directed by the BLM.

11. A new archaeological survey is not required since the existing pad will be used.

12. Lessee's or Operator's Representative:

George W. Tullos

Chevron U.S.A. Inc.
P.O. Box 1150
Midland, Texas 79702

Phone: (915)687-7463 (Office)
(915)687-3711 (Home)