

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-27601</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-906
7. Lease Name or Unit Agreement Name Amoco State
8. Well No. 4
9. Pool name or Wildcat Buckeye Abo

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Bledsoe Petro Corp.	
3. Address of Operator 3908 N. Peniel, Suite 500, Bethamy, OK 73008	
4. Well Location Unit Letter <u>N</u> : <u>360</u> Feet From The <u>South</u> Line and <u>2060</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>18S</u> Range <u>33E 33</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3917.6 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set cast iron bridge plug at 8500' spot 3 sacks cement on plug (30-35').
2. Fill 4 1/2" casing with 9.3#/gal plug mud.
3. Spot 3 sacks cement plug in 4 1/2" casing from 35' back to surface.
4. Cut off cut off 4 1/2" casing below ground level.

100' CEMENT PLUG @ TOP OF SAN ANDRES

MUST PULL OR PULL 4 1/2" CASING FROM TOP OF SALT
& PLACE CEMENT PLUG AS REQUIRE DEPENDING TO
YOU PULL OR PULL 4 1/2" USC
20 SK MIN PLUG

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Vice President DATE 5/1/91
TYPE OR PRINT NAME Gary J. Garbacz

TELEPHONE NO.

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: