Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office	
DISTRICT I OIL CONSERVATION DIVISION	WELL ADMO
P.O. Box 1980, Hobbs NM 88240 P.O. Box 2088 DISTRICT II Santa Fa. New Maxico 87504 2089	WELL API NO. 30-025-27765
P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE 6. State Oil & Gas Lease No.
	B-2229
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well:	PHILMEX
OIL GAS WELL CTHER	
2. Name of Operator	8. Well No.
Phillips Petroleum Company	17
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	9. Pool name or Wildcat MALJAMAR GRAYBURG SAN ANDRES
4. Well Location	
Unit Letter 0: 660 Feet From The FSL Line and 1	P80 Feet From The FEL Line
Section 27 Township 17-S Range 33-E	NMPM IFA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, e	NMPM LEA County te.)
Check Appropriate Box to Indicate Nature of Nation	
The control of the co	
NOTICE OF INTENTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND C	
	-
	UT, ACIDIZE, RETURN T/PROD. [X]
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103.	ates, including estimated date of starting any proposed
04/16/97 MIRU DDU, COOH W/RODS & PMP, NU BOP, COOH W/TBG, G	IH W/CSG SCRAPER & TAG @ 4635',
COOH, SD.	
04/17/97 RU TBG TSTRS, BIH W/PKR & TST TBG, SET PKR @ 4142' MIRU HES T/ACIDIZE PERFS WITH 6000 GAL FERCK SC 15	, RD IBG ISIRS, RU SWAB, WELL DR'
(A) PMP 1000 GALS ACID, (B) PMP 200 GALS 10# BRINE	CONTAINING 5003 ROCK SALT (C)
REPEAT STEPS A & B 4 MORE TIMES, (D) PMP 1000 GALS	ACID. (E) FLUSH W/40 RRIS WTR
SD, ISIP VAC, MAX PSI 835# AVG RATE 4.3 BPM, AVG P HES, RU SWAB TBG PSI 65 PSI, FL START 3600', SWAB	SI 89#, TOT LD 210 BBLS, RD MO
04/18/97 RU SWAB, TBG PSI 145 PSI, WELL DRY, COOH W/PKR, GI	DRI, REC & BBL WIR, SD. H W/PROD TRG NO ROP GIH W/PMP
& RODS, HANG WELL ON, RDMO DDU.	, riob rba, ilb bor, ulli w/riir
04/19/97 WELL TEST 9.2 OIL & 26.4 WTR, FL 4185	
(CONTINUED ON BACK)	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE ASSISTANCE A	ation Analyst DATE 04/29/97
	. ,
TYPE OR PRINT NAME Larry M. Sanders	TELEPHONE NO. (915) 368-1488
(This space for State Use) ション・ 発電で発光 は異異常 また こだい	
	DATE TO THE PARTY OF THE PARTY
APPROVED BY TITLE	DATE

PHILMEX #17 (CONTINUED)

04/20/97

TST: 12.7 OIL & 25.6 WTR.
TST: 11.02 OIL & 3.2 WTR, FL @ 4464'. 04/23/97

COMPLETE DROP F/REPORT

