

H. M. OIL CONG. COMMISSION
P. O. BOX 1880
HOBBS, NEW MEXICO 88240
UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331 for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
Sun Exploration & Production Co.
3. ADDRESS OF OPERATOR
P.O. Box 1861, Midland, Texas 79702
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: nit Letter J
AT TOP PROD. INTERVAL: 1650 FSL & 1980 FEL
AT TOTAL DEPTH: Sec. 15-19S-32E

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF:

(other) Perf Wolfcamp & acidz

5. LEASE
NM025497
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Jennings "A" Federal
9. WELL NO.
4
10. FIELD OR WILDCAT NAME
*E. Lusk (Wolfcamp)
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 15-19S-32E
12. COUNTY OR PARISH
Lea
13. STATE
NM
14. API NO.
30-025-27940
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3624' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

*TO CORRECT FIELD NAME

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10/2/85 MIRU X-pert WS/NU/BOP/ rel pkr. POH w/2-7/8 tbg & 5 1/2 RDG pkr. CRC perf Wolfcamp 10802-10818, 2 JSPF 33 holes 4" csg gun. TIH w/5 1/2 RTTS pkr on 2-7/8 tbg to 3000' SDFN/
10/3/85 Fill w/5 1/2 RTTS pkr on 2-7/8 tbg, set pkr at 10561' press annulus to 7000'. Howco acidz Wolfcamp perfs 10802-828 w/2600 gals 20% NEFEHCL acid & 81 RCNBS.
10/7/85 Rel pkr POH. TIH w/2-7/8 prod tbg & pumping setup. TS 10826. MA 10794. Perf sub 10790 SN 10789 5 1/2" Bkr TAC at 10597' w/14000# tension. ND BC/NU wellhead RIH w/2 1/2 x 1 1/2 x 24' pump on 86 rod string to 1200'. SDFN/ prep to fin POP.
10/8/85 Fill w/pump & rods spaced out. Clamped off. RR 8:30 PM 10/8/85.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Valera Reyes TITLE Sr. Accounting Asst DATE 10/25/85

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD

CONDITIONS OF APPROVAL IF ANY:

TITLE _____ DATE _____

OCT 29 1985

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

0310 : 1961 9 - 347-166

RECEIVED
OCT 31 1985
O.C.D.
HOODS OFFICE