

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

E-2519

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Conoco Inc.	8. Farm or Lease Name East EK Unit
3. Address of Operator P.O. Box 460, Hobbs, NM 88240	9. Well No. 12
4. Location of Well UNIT LETTER <u>F</u> , <u>2393</u> FEET FROM THE <u>North</u> LINE AND <u>2388</u> FEET FROM THE <u>West</u> LINE, SECTION <u>22</u> TOWNSHIP <u>18S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat EK QUEEN WEST
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1105.

1. MIRU double drum well servicing unit. P+ A the well bore by spotting cement plugs and mud plugs as follows: spot a cement plug from TD (4755') - 4468' (28.3 sx ±), spot mud from 4468' - 2010'; Spot a cement plug from 2010' - 1825' (18.3 sx ±), spot mud from 1825' - 450' (32 bbls ±), Spot a cement plug from 450' - 350' (10sx ±), WDC 1/2 - 1hr. If the top of the cement plug is below 350', fill 5 - 1/2" casing to 350' with cement, spot mud from 350' - 100'
2. Spot a cement plug from 100' - 0', cut casing 3' below restored ground level. Fill the casing from the cement plug to the surface with cement, sand, or gravel.
3. Erect a permanent steel P+ A marker, clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]

TITLE Administrative Supervisor

DATE 8-11-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE

AUG 14 1986

CONDITIONS OF APPROVAL IF ANY:

11MOR-DALLC(17)