Submit 3 Copies To Appropriate District	State of free files		Form C-103		
trict I 5 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.			
District []	d Avenue, Artesia, NM 88210 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		30-025-27953		
District III			5. Indicate Type of Lease STATE Z FEE		
000 Rio Brazos Rd., Aztec, NM 87410 istrict IV Santa Fe, NM 87505		STATE Image: State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505			K-4606		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Un	it Agreement Name:	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			State VI		
1. Type of Well:			State VI		
Oil Well Gas Well Other 2. Name of Operator Picks Exploration Inc.			8. Well No.		
2. Name of Operator Ricks Exploration, Inc.			1		
3. Address of Operator 210 Park Ave, Suite 3000, OKC, OK 73102			9. Pool name or Wildcat North Vacuum Atoka Morrow Gas		
4. Well Location					
Unit Letter P : 990 feet from the South line and 990 feet from the East line					
Section 1 Township 17S Range 34E NMPM Lea County					
10. Elevation (Show whether DR, RKB, RT, GR, etc.) GL: 4023' DF: 4054'					
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG ANI	DABANDON 🔤 🛛 R	EMEDIAL WORK		TERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMM		OMMENCE DRIL	DRILLING OPNS. PLUG AND		
PULL OR ALTER CASING MULTIPLE CASING TEST		ASING TEST AN EMENT JOB			
OTHER:	□ o	THER: Tempo	rarily Abandon	V	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.					
03/20/02					
MIRU W/O Rig. Preparing f/TA. ND Tree, NU BOP. Worked 2 hrs, unable to release On/Off tool. SDON.					
03/21/02					
MIRU W/L Truck. RIH w/1-11/16" OD Freepoint tool. Ran Freepoint Survey f/11675-11400'. Found 2-7/8" free					
@11520'. POH. RIH & cut 2-7/8" tbg @11505'. POH w/369 jts 2-7/8" 6.5# N80 EUE 8RD tbg. RIH & set 5-1/2" 20# CIBP @11490', capped w/35' cmt. RD/Rel W/L Truck. ⊺IH w/200 jts 2-7/8" tbg.					
04/18/02 Performed MIT. Witnessed by NM O	CD Representative J R	obinson Press	ured up to 540 psi an	d held for 30	
minutes with no leak off.					
	This Approval c Abandonment Exp	t Temporary	4/22/07	1	
				.	
		- former langer lande	a and haliaf		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE [aul] lag		gineer	D	ATE 4/19/02	
Type or print name Paul Legg			Telephone	No. (405) 516-1100	
(This space for State use)					
	ORIGINAL SIGNED OF GARY W. WINKLE			ACTED 2000	
Conditions of approval, if any:	OC FIELD REPRESENTA	TIVE H/STATE W	/////////////////////////////////////	2 ^E 3 2002	