		St	ate of New M	lexico					
Submit 3 copies to Appropriate District Office	1	Energy, Minerals ar	nd Natural Re	sources Department			Form C-103 Revised 1-1		
DISTRICT I	Δ	II CONSEI		NI DIVICION					
P.O. Box 1980, Hobbs, NM				DN DIVISION	WELL API NO.				
	002-10	P.	O. Box 2088	3		30-025-27973			
DISTRICT II	NIN 00010	Santa Fe, N	lew Mexico	87504-2088	5. Indicate Typ				
P.O. Box Drawer DD, Artesia	, NM 88210	•				STATE D	FEE		
DISTRICT III					6. State Oil / C	as Lease No.			
1000 Rio Brazos Rd., Aztec, NM 87410						<u>B-3011</u>			
S	UNDRY NOTICE	ES AND REPORT	IS ON WEL						
(DO NOT USE THIS FOI		SALS TO DRILL OR NR. USE "APPLICA			7. Lease Nam	e or Unit Agreement N	ame		
DIFFE		1) FOR SUCH PRO			VACUUM G	RAYBURG SAN AND	ORES UNIT		
	GAS r				1				
2. Name of Operator					8. Well No.	· · · - · ·			
TEXACO EXPLORATION & PRODUCTION INC.						62			
					9, Pool Name or Wildcat			-+	
3. Address of Operator P.O. BOX 730, HOBBS, NM 88240					VACUUM GRAYBURG SAN ANDRES				
4. Well Location									
Unit Letter	с · 6	5 Feet From		H_Line and <u>1330</u>	Feet From T	The WEST t	ine		
		<u>o </u>							
Section 2	Т	wnship 18S	R:	ange34ENN	IPM	LEA_CC	DUNTY		
	1	0. Elevation (Show whe	ether DF, RKB,	RT,GR, etc.) 4019' GR					
11.	Chaek Aser	andata Davia Ir	dianto Not	ura of Notice Deport	h as Other I				
	Спеск Аррго	opriate Box to in	idicate Nat	ure of Notice, Report	t, or Other i	Jala			
NOTICE OF	INTENTION '	TO:		SL	JBSEQUE	NT REPORT C	DF:		
		JG AND ABANDON		REMEDIAL WORK		ALTERING CASING			
PERFORM REMEDIAL WOR			=					Ц	
TEMPORARILY ABANDON		ANGE PLANS		COMMENCE DRILLING OPE		PLUG AND ABANDO	NMENT		
PULL OR ALTER CASING				CASING TEST AND CEMEN	ит ЈОВ 🔲				
OTHER:			П	OTHER:	CLEANOUT, AD	DED PAY, ACIDIZED		\boxtimes	
 4/4/95 - 4/12/95 MIRU, installed BOP. T TIH w/ 4 3/4" bit & 2 3/8" TIH with 5 1/2" X 2 3/8" f Acidized perfs from 4516 Released packer. TOH 4448'-4454', 4462'-4466 TIH with 5 1/2" RBP, 5 1 top San Andres perforati Pull up & set packer @ 4 treating pressure of 4000 TIH w/ 5 1/2" x 2 3/8" AU with packer fluid. Pressure OPT 4/24/95 INJECTIN 	workstring. Tagg reating packer & 2 5'-4755' w/ 4000 ga with WS & packer. ', 4524'-4530', and /2" X 2 3/8" treating on @ 4546'). 1344'. Acidized net) psi. SI 1 hr. Swa D-1 injection packet ure tested casing to G 337 BWPD @ 1	ed fill @ 4460'. C/O 3/8" WS. Set packet als of 20% NEFE HC Perforated the follor 4532'-4538' (100 hc g packer, and 2 3/8" w perforations (4394 ab back load. TOH w r on 2 3/8" J-55 Rice 5 570# for 30 min, he 042 PSI	er @ 4400'. P Cl. Max P = 27 wing intervals bles). workstring. S I'-4538') w/ 500 w/ RBP, treatin e Duoline inject eld ok. Return	ickled tubing w/ 450 gals 1 700#, AIR = 4.1 BPM. with 2 JSPF: 4394'-4405' et RBP @ 4545' (bottom G 00 gals of 20% NEFE HCI ng packer, & WS. tion tubing. Set injection pa	5% NEFE HCI , 4418'-4431', Grayburg perfor @ 3 to 4 BPM	4436'-4439', ation @ 4538'; w/ a maximum			
(ORIGINAL CHART ATT (INTERNAL TEPI STAT I hereby certify that the information above SIGNATURE	US WILL REMAIN	I INJ) best of my knowledge and belle TI e C. Duncan		Asst		DATE <u>6/2</u> Telephone No.	/ <u>95</u> 397-0418		
(This space for State Use)		SIGNED BY							
APPROVED BY	GARY		LE			DATE	<u>N 05 1</u>	995	

CONDITIONS OF APPROVAL, IF ANY: FIELD REP. IT

DeSoto/Nichols 10-94 ver 2.0

