

NEW MEXICO AE ST. #26
ESTIMATE NO. 3-5968
DRILL

TOTAL DEPTH 8850'
PLUB BACK TOTAL DEPTH 8840'

13 3/8" OD 48# H-40 CASING SET @ 350'
8 5/8" OD 32# S-80 24# J-55 & 32# J-55 CSG SET @ 3139'
5 1/2" OD 15.5# & 17# J-55 CSG SET @ 8850'

1. PERFORATE 5 1/2" CASING W/2-JSPF @ 8765', 70', 78', 85', 98', 8804', 12', & 8820'.
2. SET PACKER @ 8700'. ACIDIZE PERFS. 8765' - 8820' W/ 2500 GALS. 15% NE ACID & 20 BALL SEALERS.
3. ACIDIZE PERFS. 8765' - 8820' W/8000 GALS. 15% NE ACID AND 32 BALL SEALERS.
4. PERFORATE 5 1/2" CASING W/2-JSPF @ 8580', 90', 93', 8608', 12', 20', 25', 45', 50', 52', 59', 70', 83', 8702', 13', 20', 23', 36', & 8742'.
5. SET RBP @ 8752'. PACKER SET @ 8526'. ACIDIZE PERFORATIONS 8580' - 8742' W/3000 GALS 15% NE ACID, 55 GALS SCALE INHIBITOR AND 80 BALL SEALERS.
6. PULL RBP & PACKER. PERFORATE 5 1/2" CASING W/2-JSPF @ 8327', 30', 34', 38', 45', 50', 54', 56', 62', 68', 73', 78', 83', 88', 94', 8400', 06', 11', 14', 18', 21', & 8429'.
7. SET RBP @ 8495' AND PKR @ 8277'. ACIDIZE 5 1/2" CASING PERFS 8327' - 8429' W/5000 GALS 15% NE ACID AND 88 BALL SEALERS.
8. INSTALL PUMPING EQUIPMENT. TEST AND PLACE ON PRODUCTION.