

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

API #30-025-28411

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒	GAS WELL ☐	OTHER ☐	5c. Indicate Type of Lease State ☒ Fee ☐
NAME OF OPERATOR SHELL WESTERN E&P INC.			7. Unit Agreement Name N. HOBBS (G/SA) UNIT
ADDRESS OF OPERATOR P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)			8. Form of Lease (Name) SECTION 33
LOCATION OF WELL UNIT LETTER M 1250 FEET FROM THE SOUTH LINE AND 185 FEET FROM THE WEST LINE, SECTION 33 TOWNSHIP 18-S RANGE 38-E N.M.P.M.			9. Well No. 142
10. Field and Pool, or Whichever HOBBS (G/SA)			
11. Elevation (Show whether DF, RT, GR, etc.) 3635.1' GL			12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER ☒ SQZD, REPERF'D & ACD

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.)

5-01 to 5-02-86: Pulled production equipment. POH w/RBP @ 4058'. Set CIBP @ 4050'. Set CIGR @ 3907'. Attempd sqz of San Andres perfs 4027' - 4040' w/75 sx Cls "C" cmt + .2% Halad-4 + 2% CaCl₂ followed by 25 sx Cls "C" cmt + 2% CaCl₂. No sqz pres.

5-03-86: Sqzd perfs 4027' - 4040' w/100 sx Cls "C" cmt + 2% CaCl₂. Dmpd 10' cmt on CIGR @ 3907'.

5-05 to 5-07-86: Drld out cmt (& CIGR @ 3907') to 4050'. Circ'd clean. Pres tstd sqzd perfs 4027' - 4040' to 1000# for 10 min, held OK. Drld out CIBP @ 4050'. Drld out cmt 4068' - 4242'. Circ'd clean. Pres tstd 5-1/2" csg against all perfs to 500# for 10 min, held OK. Reperf'd San Andres 4068' - 4172' (2 JSPF, 26 holes).

5-08-86: Acd perfs 4068' - 4172' w/1250 gals 15% HCl + 14# citric acid.

5-09-86: Installed production equipment and returned well to production.

NSL-1749

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

By A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MAY 30, 1986
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR
APPROVED BY _____ TITLE _____
JUN 8 1986