Fo (Ju

J.	M_	OIL	CONS.	COMMISSION
٠.			1000	

- The Company of August 1 Au

orm 3160-5 une 1990)			NT OF THE IN	TEDIOD	MORRE NEV	MEXICOBURE 29 9004-0135	
unc 1990)			LAND MANA		11000001	Expues. Water 31, 1993	
	DOF	EAU OF	LAND MANA	GEMENT		5. Lease Designation and Serial No.	
	SUNDRY I	NOTICES	AND REPOR	TS ON WELLS		NI: 1 4609 6. If Indian, Allottee or Tribe Name	
Do not	use this form for propo Use "APPLIC			n or reentry to a di for such proposals		6. at Distant, Allottee of 1 fibe Name	
1. Type of V	1.41	SUBMIT	T IN TRIPLICA	ATE		7. If Unit or CA, Agreement Designation	n
Oil Well	Gas Well Other					8. Well Name and No. 2P2H	5
2. Name of	•					Federal "E" #9 -	۲2
Mewbo	ourne Oil Company Ind Telephone No.					30-025-28493	
	Box 5270 Hobbs,	New Me	xico 88241	(505) 393-590	\E		
	of Well (Footage, Sec., T., R., M	10. Field and Pool of Explorator Area					
1000	1 EN 8 2201 EEL				1	Oueen Assoc 11. County or Parish, State	
	' FNL & 330' FEL 28-T18S-R32E						
Sec.	20-1103-K32E					Lea County, N.M.	
2.	CHECK APPROPRIA	TE BOX	(s) TO INDICA	ATE NATURE OF	NOTICE, REPOR	T, OR OTHER DATA	_
	TYPE OF SUBMISSION]		TYPE OF ACTION		
	Notice of Intent			Abandonment		Change of Plans	
				Recompletion		New Construction	
	Subsequent Report			Plugging Back	-	Non-Routine Fracturing	
				Casing Repair		Water Shut-Off	
*	Final Abandonment Notice	•		Altering Casing		Conversion to Injection	
			1	Other		Dispose Water	
						(Note: Report results of multiple completion on W Completion or Recompletion Report and Log for	m ì
3. Describe : give	Proposed or Completed Operations subsurface locations and measured	(Clearly state a and true verti	all pertinent details, and ical depths for all mark	give pertinent dates, including kers and zones pertinent to the	ig estimated date of starting a his work.)*	my proposed work. If well is directionally dri	illed
•	•		•	•			
	<u>Date</u>	<u>Operat</u>	<u>tion</u>				
	9-26-94	MIRU 1	workover i	rig. LD all	rods and pur	mp.	
	9-27-94		with tbg.				
	9-28-94	TIH w	ith PKR. S	Set PKR at 3	793'.		
	9-28-94	ACIG12	zed perfs	with 2,000	gals Ne-Fe a	acid.	
	10-6-94		workover i				
	10 0 34	nan m	ure charts	ilus. OCD re	p present ar		
		presse	ure charts	5 •		RI OCT 18 AREA	
					•		
						I 39	
					2 19 94	39 VE	
		•				9 FI	
					30		
						සි <u>ල</u> ල්	
4. I hereby	certify that the foregoing is true an	d correct					=
Signed _	MK LHOW		TitleF	Petroleum Engi	neer	Date October 12, 1994	1_
(This spe	ce for Federal or State office use)						=
Approved	d by		Title			Date	
Condition	s of approval, if any						