Submit to Appropriate District Office State Lease - 6 copies Fee Lease - 5 copies	Energy,	State of New Me Minerals and Natural Re				Form C-1		
		CONSERVATION DIVISION P.O. Box 2088		API NO. (at	API NO. (assigned by OCD on New Wells)			
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, N		Santa Fe, New Mexico 87504-2088		5. Indicate	Type of Lease	ate XX	FEE	
DISTRICT III 1000 Rio Brazos Rd., Azteo	, NM 87410			6. State Oil	& Gas Lease	No.	5188	
APPLICAT	ION FOR PERMIT	TO DRILL, DEEPEN, C	OR PLUG BACK		7//////////////////////////////////////	///////////////////////////////////////	777777	
1a. Type of Work:				7. Lease N	ame or Unit Ag	reement Name		
DRILL b. Type of Well: OIL GAS WELL X WELL	C RE-ENTER	DEEPEN SINGLE ZONE	PLUG BACK		State "H	-		
2. Name of Operator				8. Well No	•			
	Meridian Oil	Inc.			7			
3. Address of Operator	21 Desta Dri	ve, Midland, TX	79705		neorWildcat p (Bone	Springs)		
4. Well Location Unit Letter	1_: <u>660</u> Feet F	rom The South	Line and 6	60 Feet	From The	West	Line	
Section 20) Towa	hip 18 South Rad	nge 34 East	NMPM		Lea	County	
10. Proposed Depth11. Formation9112' - 9168'1st Bone State					nning Sa	12. Rotary or C	C.T.	
13. Elevations (Show whethe	r DF, RT, GR, etc.)	4. Kind & Status Plug. Bond	15. Drilling Contracto		,			
3992.5 GR				•	16. Approx. Date Work will start 03/01/89			
17. In Place No	DW PR	OPOSED CASING AN	ID CEMENT PROG	BAM				
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF	CEMENT	EST.		
17 1/2"	13 3/8"	54.5	325'		00010111			
12 1/4"	8 5/8"	32	4,000'					
7 7/8"	5 1/2"	15 1/2 & 17	10,885'					

Meridian proposes to plug back and temporarily abandon the Wolfcamp and recomplete the well in the First Bone Spring Sand.

See attached procedure:

.

CONDITIONS OF APPROVAL, IF ANY:	Permit Expires & Months From	Approval
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	1111 B	FEB 27 1989
TYPE OR PRINT NAME ROBERT L. Bradshaw		TELEPHONE NO.915-686-56
I hereby certify that the information above is true and complete to the best of my know SKINATURE RELEVER E. B. 20 Ch. Lague	<pre>//edge and belief. </pre>	DATE 02/24/89

Date Unless Drilling Underway.

•

فالوديور والمتوور المرايين

State "HQ" No. 7 Airstrip (Bone Spring) Field Lea County, New Mexico

- 1. MIRU pulling unit. POH with rods and pump. ND pump tee. NU BOP. with ±10,700' of 2-7/8" 6.5# N-80 tubing. POH
- 2. MIRU wireline unit. RIH with a gauge ring and junk basket for 5-1/2" 17# casing to $\pm 10,650'$. POH. RIH with a 5-1/2" CIBP on wireline and set at ±10,650'. POH. Load 8-5/8" x 5-1/2" annulus and pressure test 5-1/2" casing to 4000 psi. RIH with 4" select fire guns and perforate the Bone Spring Sand at the following depths: 9113', 18', 20', 26', 32', 34', 36', 38' 40', 42', 45', 47', 51', 53', 55', 57', 59', 62', 64' and 68' for a total of 20 holes. POH. RDMO wireline unit.
- 3. RIH with a 5-1/2" treating packer, SN (2.25" ID) and ±9000' of 2-7/8" tubing. Hydrotest tubing to 7000-psi while RIH. Set packer at ±9000' and swab well down to SN if possible.
- 4. MIRU stimulation company. NU surface lines and test to 4000 psi. Place, monitor and maintain 500 psi on the casing-tubing annulus. Pump 2000 gallons of 7-1/2% NEFe HCl acid with 2 gal/1000 surfactant and corrosion inhibitor. Space out 40 - 7/8" RCNBS (sp.gr.= 1.3) throughout job. Displace acid with 54 bbls of 2% KCl water. If ballout occurs, surge balls off perfs and continue displacement.
 - * Note: Anticipated treating pressure = 3300 psi Maximum treating pressure = 4000 psi (Burst SF = 2.6) Anticipated treating rate = 4 BPM

RDMO Stimulation Company.

- 5. Swab test well recording rates and cuts.
- 6. If fluid entry is limited, release packer run through perfs and POH with tubing. MIRU stimulation company. NU surface lines and test to 6000 psi. Pump 26,000 gallons of 40 lb. crosslinked gel with 61,000 lbs. of 16/30 mesh PRC sand to frac the First Bone spring Sand down 5-1/2" casing according to the following schedule and attached sheets.
 - Pump 8,000 gallons of fluid as pad volume.
 - Pump 2,000 gallons of fluid with lppg 16/30 PRC sand.
 - Pump 3,000 gallons of fluid with 2ppg 16/30 PRC sand.
 - Pump 4,000 gallons of fluid with 3ppg 16/30 PRC sand.

RECEIVED FEB 27 1989 OCD MORE OTHER

State "HQ" No. 7 Airstrip (Bone Spring) Field Page Two of Procedure

- Pump 4,000 gallons of fluid with 4ppg 16/30 PRC sand.
- Pump 5,000 gallons of fluid with 5ppg 16/30 PRC sand.
- * Note: Anticipated treating pressure = _3700 psi Maximum treating pressure = 4000 psi (Burst SF = 1.2) Anticipated treating rate = 20 BPM

RDMO stimulation company. Shut well in overnight to allow gels to break.

- 7. Flow well back starting at ±16/64 choke increasing choke size as the pressure depletes. Obtain flow back fluid and have analyzed at pressure depletes. Obtain flow back fluid and have analy stimulation company. Viscosity of the broken gel should be ±10 cp.
- 8. RIH with a notched collar on 2-7/8" tubing and clean out any fill to
- 9. RIH with production tubing and rods as previously installed setting pump at $\pm 9050'$ to clean up frac. Lower pump to $\pm 9200'$ following clean up



MERIDIAN OIL



SCALE: 1" = 1000'

OPERATOR: MERIDIAN OIL INC.

FIELD: Airstrip (Bone Spring)

LEASE: State "HQ"

Well No.: 7

LOCATION: 660' FSL & 660' FWL; Sec. 26, T-18-S, R-34-E, Lea County