## State of New Mexico erals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088		WELL API NO.		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210  Santa Fe, New Mexico 87504-2088		30-025-28790  5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			STATE X FEE  6. State Oil & Gas Lease No.	
			LG-342	5
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
I. Type of Well: OIL GAS WELL X WELL	CT CAS CT		Compton State	
2. Name of Operator		1.5	8. Well No.	
YATES PETROLEUM CORPOR	RATION		1	
	et - Artesia, NM 88210	·	9. Pool name or Wildcat Airstrip Bone S	Springs
4. Well Location  Unit LetterC :330	Feet From The North	Line and1980	Feet From The	West Line
Section 35			<b>NMPM</b> Lea	County
	10. Elevation (Show whether			
11. Check	Appropriate Box to Indicate 1		eport, or Other Data	
NOTICE OF IN	** *		SEQUENT REPO	
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTER	RING CASING
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING			G OPNS. PLUG	AND ABANDONMENT X
PULL OR ALTER CASING CASING TEST AI			EMENT JOB	
OTHER:		OTHER:		
12. Describe Proposed or Completed Open work) SEE RULE 1103.	utions (Clearly state all pertinent details, ar	d give pertinent dates, inclu	iding estimated date of startin	g any proposed
1-18-95 - Moved in and laid down 12 fiberglas of 2-7/8" tubing. Pic down total of 70 rods. 1-19-95 - POOH with tu Laid down rods. POOH laid down and cut rods fiberglass rods. Cut 1-20-95 - POOH with tu RIH w/5-1/2" CIBP and tagged CIBP. Spotted	rigged up pulling unit. s rods. Nippled down we ked up on rods - pump st Shut down for night. bing to top of rods. At with tubing. Attempted Pulled up to 1" steel 4 rods. Laid down 168 bing, seating nipple, pe set at 9110'. Rigged do 143 bbls plug mud from 9 Mixed and pumped 25 sac n overnight.	lihead. Nippleduck. Worked and tempted to back to back off rode. Tods. Backed all steel rods. For sub and tubic own wireline. Reliable 110-3000'. Pre	d up BOP. POOH we departed rods. Pooff bottom. Pars. Parted high. off pump. Laid down for ning anchor. Rigger IH w/tubing to 91 ssure tested 5-1/	rith 18 joints 200H. Laid Tted high. POOH and lown 106 Light. Ed up wireline. 110' and 2'' casing to
I hereby certify that the information above is at	se, and complete to the best of my knowledge and	belief.		
SIGNATURE USTIN	// /	ne Production	Clerk D	ATE2-6-95
TYPEOR PRINT NAME Rusty Klein			TE	005-748-1471 ELEPHONE NO.
(This space for State Use)	(1) [[in]	il & Gas ins		MAR 2,4,1995
APTROVED BY ANY A	т	TE ————	D	ATTE WINDE