

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

API #30-025-28879

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name SECTION 24
3. Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)	9. Well No. 414
4. Location of Well UNIT LETTER <u>A</u> <u>10</u> FEET FROM THE <u>NORTH</u> LINE AND <u>1280</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>24</u> TOWNSHIP <u>18S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool, or Whdcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3671.1' GL	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☒ WSO, OAP & ACD

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-21-88: POH w/prod equip. CO to 4321'.

3-22-88: Set CIBP @ 4245' & CIGR @ 4130'. Attempd to sqz San Andres perms 4216'-39' w/78 sx Cls "C" cmt + 200 SCF N₂. No sqz, displaced cmt w/10 bbls fresh wtr. Sqzd w/75 sx Cls "C" cmt + 2% CaCl₂.

3-23 to 3-24-88: DO cmt (& CIGR @ 4130') 4128' - 4245'. Pres tstd sqz to 500# for 15 min, held OK. DO CIBP @ 4245' & cmt to 4323'. CO to PBD @ 4325'.

3-25-88: Perf'd San Andres 4252'-83' (2 JSPF, w/4 shots @ 4265'). Acd perms 4252'-83' w/ 750 gals 15% HCl + 150# rock salt. Perf'd San Andres 4181'-98' (2 JSPF). Set RBP @ 4212'. Acd perms 4181'-98' w/450 gals 15% HCl + 150# rock salt.

3-26 to 3-27-88: POH w/RBP. Installed prod equip & returned well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE

TITLE SUPERVISOR REG. & PERMITTING

DATE 4-19-88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

TITLE

DATE APR 25 1988

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY: