

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

FILE IN TRIPLICATE

**OIL CONSERVATION DIVISION**

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

2040 Pacheco St.  
Santa Fe, NM 87505

DISTRICT II  
811 S. 1st Street, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd. Aztec, NM 87410

WELL API NO.	30-025-28958
5. Indicate Type of Lease FED <input checked="" type="checkbox"/> STATE <input type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT	
8. Well No.	443
9. Pool name or Wildcat	HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3648 GL	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Injector <input type="checkbox"/>	2. Name of Operator Occidental Permian Ltd.
3. Address of Operator 1017 W. Stanolind Rd., HOBBS, NM 88240	505/397-8200
4. Well Location Unit Letter <u>P</u> : <u>1300</u> Feet From The <u>SOUTH</u> Line and <u>106</u> Feet From The <u>EAST</u> Line Section <u>30</u> Township <u>18S</u> Range <u>38E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3648 GL	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: Convert to Pressure Observation well ☒

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS ☐ PLUG & ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  
SEE RULE 1103.

- 1 Pull injection equipment
- 2 Set plug over lower San Andres perfs at approx 4070'
- 3 Perf upper San Andres
- 4 Run tubing and packer use well to monitor reservoir pressure.

Federal Form 3160 will be filed

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PROD ENGR DATE 3-13-03  
TYPE OR PRINT NAME D. NELSON TELEPHONE NO 505 397-8200

(This space for State Use)

APPROVED BY GARY W. WINK DATE MAR 19 2003  
CONDITIONS OF APPROVAL IF ANY: