Form 3160-5 UNITED S TES SUBMIT IN TRIPLICAT (Other Instructions on Formerly 9-331) DEPARTMENT OF THE INTERIOR verse aide)	Budget Bureau No. 1004-0135 Expires August 31, 1985 LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL GAS INJECTOR 2. HAME OF OPERATOR	7. UNIT AGREEMENT NAME N. HOBBS (G/SA) UNIT 8. FARM OR LEAGE NAME
SHELL WESTERN E&P INC.	SECTION 30
P.O. BOX 991 HOUSTON TX 77001 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1300 FSL & 160 FEL	9. WELL FO. 443 10. FIELD AND POOL, OR WILDCAT HOBBS (G/SA) 11. SEC., T., R., M., OR RLE, AND SURVEY OR AREA
14. PERMIT NO. 15. BLEVATIONS (Show whether DF, BT, GR, etc.) NA 3657.5' DF; 3647.5' GL	SEC. 30, T18S, R38E
NA 3657.5' DF; 3647.5' GL Check Appropriate Box To Indicate Nature of Notice, Report, or	LEA NEW MEXICO
	FOTHER DOTO
(Other) (Norx: Report resu	T.O.C. TO SURFACE X with of multiple completion on Well upletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dat proposed work. If well is directionally drilled, give subsurface locations and measured and true ver nent to this work.) 1-16-85: Ran bit to 2927' & hit cmt. Drilled cmt from 2927' @ 3058'. Ran bit to 4270' & hit float collar. Dri	to 3058'. Drilled DV tool
to 4295'. 1-17-85: Ran CBL from 4290' - 4000'. Ran CBL from 4290' - s 3600'. Ran BHCS from 4290' - 3600'. Ran CNL from 858'. Contacted BLM engineer, got OK to complete w	4290' - 3600'. Top of cmt @
16. I bereby certify that the foregoing is true and correct	TC EEDDUADY 26 1006
SIGNED CITE FOR A. J. FORE TITLE SUPERVISOR REG. & PERMI	TS DATE FEBRUARY 26, 1985
APPROVED BY	DATE
MÁR Ó BÍRES	

*See Instructions on Reverse Side