

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR N L
OF COPIES RETURNED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
M100-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		3a. Area Code & Phone No. 505-393-2727		5. LEASE DESIGNATION AND SERIAL NO. NM-0245247	
2. NAME OF OPERATOR C. W. Trainer				6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR c/o Oil Reports & Gas Services, Inc., Box 755, Hobbs, NM 88240				7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1980' FEL of Section 25				8. FARM OR LEASE NAME McElvain	
10. PERMIT NO. API #30-025-28997		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3883 KB		9. WELL NO. 4	
				10. FIELD AND POOL, OR WILDCAT EK Bone Spring	
				11. SEC., T., R., M., OR BLK. AND SUBST OR AREA Sec 25 T18S R33E	
				12. COUNTY OR PARISH Lea	
				13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

FILL OR ALTER CASING
MULTIPLE COMPLETION
ABANDON*
CHANGE PLANE

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

Perf Additional Bone Spring

(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work began 8/23/91. Perforate 9684 to 9775 with 56 holes. Set packer at 9633 and treat with 2,000 gallons 7 1/2% SRA HCL acid. Swab load. Frac with 60,000 gallons Apollo III, 157,000# sand & 97 tons CO2. Flow & swab load. Ran bailer & clean out to 9937. Ran tubing, pump and rods. 9/17/91 pump 70 bbls oil, 2 bbls water, 91 MCF gas 24 hours.

18. I hereby certify that the foregoing is true and correct

SIGNED

Donna Holler

TITLE

Agent

DATE

10-17-91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side