

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
<u>E-1632</u>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>State 27</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, NM 88240</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>P</u> <u>260</u> FEET FROM THE <u>south</u> LINE AND <u>660'</u> FEET FROM THE <u>east</u> LINE, SECTION <u>27</u> TOWNSHIP <u>18S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat <u>Under Bone Springs</u> <u>Wedge camp</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work started on 2/27/87 and completed 3/3/87. G11H w/ 290' of 2 3/8" Hbg to 9020'. Circ wellbore w/ 345 bbls of 9.5 ppq mud (9 ppq brine mixed w/ 25 sxs salt gel per 100 bbl brine). Spot 16 sxs class "c" neat cmt from 7646' - 7546'. Spot 16 sxs cmt from 4048' - 3948'. Spot 5 bbls 10% acetic acid from 1500' - 1369'. Shoot 4 jspF at 1500'. Pump in rate of 1/2 BPM at 2000 psi. Did not circ. Spot 16 sxs class "c" neat from 1550' - 1450'. Shoot 4 jspF at 435'. Pump down 7" csq & establish circ. Amp 135 sxs class "c" neat down csq & circ 5 sxs. Left top of cmt in 7" at surface. Rig down. install dry hole marker.

nmoc6(3) file

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]

TITLE Administrative Supervisor DATE April 14, 1987

APPROVED BY [Signature]

TITLE OIL & GAS INSPECTOR

DATE AUG 4 1987

CONDITIONS OF APPROVAL, IF ANY: