State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL C	CONSERV	ATION I	DIVISIO	N				
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St.				WELL A	WELL API NO. 30-025-29062			
					5 Indies	5. Indicate Type of Lease			
DISTRICT II	•0				FEI		TATE X	FEE.	7
811 S. 1st Street, Artesia, NM 882	10					Oil & Gas Lease		<u> </u>	
DISTRICT III	7410				0.500	o			
1000 Rio Brazos Rd. Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS									
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						7. Lease Name or Unit Agreement Name			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"									
(FORM C-101 FOR SUCH PROPOSALS.)						H HOBBS (G	/SA) UN	TT	
Type of Well: Oil Well	X Gas Well	Other							
2. Name of Operator						8. Well No. 342			
ALTURA ENERGY LT	<u>D.</u>				9 Pool	name or Wildcat	1	HOBBS (G/SA	$\overline{}$
3. Address of Operator 1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200						name or whoest	1	IODDS (GISA	'
4. Well Location	HOBBS, NM 88240	503/3:	97-0200						
Unit Letter O	145 Feet From The	SOUTH	Line and	1435	Feet From The	EAST	I	ine	
Section 24	Township	18S		Range	37E	NMPM		LEA County	,,,,,,,,,,
	10. Elevation (Sho 3665 GL	w whether DF, R	KB, RT GR, etc	.)					
<u>/////////////////////////////////////</u>	Check Appropriate Box	to Indicate N	ature of Not	ice, Repor	t, or Other Dat	a			
	OF INTENTION TO:			, ,	SUBSEQUE	NT REPOR	RT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABAN	DON	REMEDIA	L WORK		ALTI	ERING CA	ASING	Ш
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI						PLU	IG & ABA	NDONMENT	
PULL OR ALTER CASING			CASING	EST AND	CEMENT JOB				
OTHER: Convert to Wat	or Injection	X	OTHER:						
	ted Operations (Clearly state all per		d ama partina	t datas inch	uding estimated de	ate of starting ar	v propose	d work)	
 Describe Proposed or Complet SEE RULE 1103. 	ed Operations (Clearly state all per	rtinent aetaiis, ar	ia give periine.	n aates, men	aamg estimatea ac	ne of starting an	iy propose	<i>a 110/11</i> /	
JEI, ROBE 1100.									
 Pull production equipment 									
2. Drill out CIBP's at 411									
3. Squeeze perfs from 40:4. Perforate lower San Ar									
 Perforate lower San At Run injection equipme 									
6. Test packer and wait to									
	J								
		NIMOCID							
Will not commence injection	on until permit is approved by	NMOCD.							
_									
I hereby certify that the informati	on above is true and complete to the	best of my know	ledge and belie	f.			-		
Thereby certify that the that the		*			NOR		DATE	11/2.19	S
SIGNATURE	140900		TITLE	PROD E	NGR	TELEPHO		505/397-8200	
TYPE OR PRINT NAME						TELEPHO	NE. INC.	コロコ/コンフ-8200	
	D. NELSON) 8 7						1,24	==
(This space for State Use)	ORIGINAL	· BY				1232116	Į.	الم	<u> </u>
	ORIGINAL GARY WINK FIELD REPORT) BV	TITLE					الا (الله الله الله الله الله الله الله	

6/*

محاسبهن ا