

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES DESIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

API #30-025-29064

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name SECTION 30
3. Address of Operator P.O. BOX 991, HOUSTON, TX 77001	9. Well No. 113
4. Location of Well UNIT LETTER <u>D</u> <u>1310</u> FEET FROM THE <u>NORTH</u> LINE AND <u>195</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>30</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> N.M.P.M.	10. Field and Pool, or Widcon HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3657.9' GL	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

1-8-85: Ran 107 jts (4393') 5-1/2" 14# K-55 ST&C csg, guide shoe @ 4362', cmt'd w/440 sx Lite w/2% D-20 & 8.43#/sx D-44 + 220 sx Hi-Early II w/1/2#/sx D-29 + 330 sx Hi-Early II w/4.87#/sx D-44. Circulated out 66 sx cmt, bumped plug w/2200 psi @ 8:00 PM 1-7-85, held OK. WOC time 8 hrs on 1-8-85, RIG RELEASED @ 4:00 AM 1-8-85.

NSL Order R-7628

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JANUARY 24, 1985

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE

JAN 28 1985

RECEIVED

JAN 28 1985

C. C. B.
MODERATOR