

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

API #30-025-29074

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name SECTION 32
3. Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)	9. Well No. 422
4. Location of Well UNIT LETTER H 1385 FEET FROM THE NORTH LINE AND 110 FEET FROM THE EAST LINE, SECTION 32 TOWNSHIP 18-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3651.4' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☒ OAP & ACDZ

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. POH w/prod equip.
2. CO to 4250'.
3. Perf San Andres 4051' - 4175' (2 JSPF).
4. Acdz perms 4051' - 4175' w/500 gals 15% HCl.
5. Install prod equip & return well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. F. N. Kelldorf TITLE STAFF PRODUCTION ENGINEER DATE 4-13-88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE APR 18 1988

CONDITIONS OF APPROVAL, IF ANY: