

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other <u>Dry Hole</u>	5. LEASE NM-12277
2. NAME OF OPERATOR Sun Exploration & Production Co.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 1861, Midland, Texas 79702	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1980' FSL & 660' FEL of AT TOP PROD. INTERVAL: Sec. 29-18S-34E AT TOTAL DEPTH: Unit Letter I	8. FARM OR LEASE NAME Pennzoil "A" Federal
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	9. WELL NO. 1
	10. FIELD OR WILDCAT NAME (EK East) Undesignated Bone Springs
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29-18S-34E
	12. COUNTY OR PARISH Lea
	13. STATE NM
	14. API NO.
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3970' GR

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF ☐	☐
FRACTURE TREAT ☐	☐
SHOOT OR ACIDIZE ☐	☐
REPAIR WELL ☐	☐
PULL OR ALTER CASING ☐	☐
MULTIPLE COMPLETE ☐	☐
CHANGE ZONES ☐	☐
ABANDON* ☐	☒
(other) _____	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5/29/85 TIH w/DCS LD DCS. TIH w/DP GE to 9650'.
Spot a 45 sks C1 H cmt plug fm 9650 to 9800'. Spot a 45 sks C1 H cmt plug fm 7925 to 7775. Spot a 45 sks C1 H cmt plug fm 6825-6675. Spot a 45 sks C1 H cmt plug fm 5560-5410. Spot a 35 sks C1 H cmt plug fm 4614-4500, contacted Ralph Dillow w/BLM at 2:00 pm prior to plugging. Spot 35 sks C1 H cmt plug fm 3750-3650. Spot 35 sks C1 H cmt plug fm 3200-3100. Spot 35 sks C1 H cmt plug fm 1945-1845. Spot 35 sks C1 H cmt plug fm 400-300. Spot 20 sks C1 H surf plug. NO BCPS jet pits. Cut off wellhead 5' BGL. Weld on steel plate & dry hole marker. Well PSA.

Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Elma Reyes TITLE Sr. Accting. Asst. DATE 9/5/85

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 13 1985

O.C.R.
HOBBS OFFICE