

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI  
(Other instructi  
verse side)

CATS  
NO 70

Form approved  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

|                                                                                                                                                                            |                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection                                           | 5. LEASE DESIGNATION AND SERIAL NO<br>NMLC029489B                   |
| 2. NAME OF OPERATOR<br>OXY USA Inc.                                                                                                                                        | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME                                |
| 3. ADDRESS OF OPERATOR<br>P.O.Box 50250 Midland, TX. 79710                                                                                                                 | 7. UNIT AGREEMENT NAME                                              |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.<br>See also space 17 below.)<br>At surface<br>660 FSL 1980 FEL Sec 4 T18S R33E | 8. FARM OR LEASE NAME<br>Central Corbin Queen Ut                    |
| 14. PERMIT NO.<br>300252932500S01                                                                                                                                          | 9. WELL NO.<br>201                                                  |
| 15. ELEVATIONS (Show whether DF, RT, CR, etc.)                                                                                                                             | 10. FIELD AND POOL, OR WILDCAT<br>Corbin Queen, Central             |
|                                                                                                                                                                            | 11. SEC., T., R., N., OR S.E. AND SURVEY OR AREA<br>Sec 4 T18S R33E |
|                                                                                                                                                                            | 12. COUNTY OR PARISH<br>Lea                                         |
|                                                                                                                                                                            | 13. STATE<br>NM                                                     |

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANT

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Other) Convert to Water Injection

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TD - 4300' PBTD - 4256' Perfs - 4221-4241'

- 1) MIRU PU. TOOH & LD pump & rods. NDWH, NUBOP. TIH w/ tbg & tag PBTD. TOOH w/ tbg.
- 2) TIH w/ RB & tbg & CO fill to PBTD. TOOH w/ RB & tbg.
- 3) TIH w/ pkr & 2-3/8" tbg & set @ 4130'. Acidize Queen perfs 4221-4241' w/2500 gal 15% NeFe HCl acid & flush w/2% KCl wtr.
- 4) Swab back load.
- 5) TOOH w/ pkr & tbg. TIH w/ injection pkr & 2-3/8" tbg & set @ 4130'. NDBOP, NUWH, RDP. Run csg integrity test.

18. I hereby certify that the foregoing is true and correct

SIGNED

David Stewart

TITLE Prod. Acct.

915-685-5717

DATE 9/12/91

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

PETROLEUM ENGINEER

DATE 9/21/91

Subject to  
Like Approval  
by State

\*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

23.

SEP 24 1991

1001

ACADES OFFICE