

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator
Santa Fe Exploration, Inc.
Address of Operator
P. O. Box 1136, Roswell, NM 88202-1136
Location of Well
UNIT LETTER L 1650 FEET FROM THE South LINE AND 330 FEET FROM
THE West LINE, SECTION 3 TOWNSHIP 18S RANGE 33E N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name
Corbin Fee
9. Well No.
#2
10. Field and Pool, or Wildcat
Undesignated
12. County
Lea

15. Elevation (Show whether DF, RT, CR, etc.)
4012.1 G.L.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUS AND ABANDONMENT ☐
TEAR OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER <u>Set & Cement Production Casing</u> ☒

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-19-85 TD 5200'. Ran 123 jts (5213') 5 1/2" 17# csg. Set & cemented @ 5200' w/350 sx
C1 "C" 50/50 POZ w/4% Bentonite, 5#/sk salt. PD @ 5:00 PM on 7-19-85.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerraine Schmitt TITLE Production Analyst DATE 7/24/85
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR
APPROVED BY _____ TITLE _____ DATE AUG - 5 1985
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG - 5 1985

1000 5700