J.M. HUBER CORPORATION FEDERAL "27" NO. 2 FORM 3160-5 (cont'd) SESE/4, Sec. 27. T18S, R33E

- 12/6/85 Acidize perfs. 8828-897' w/15% spearhead acid & nitrogen. Swab Test; emulsion.
- 12/9/85 Treat perfs. 8828-897' w/116 bbls heated lease crude with surfactant. Swab test.
- 12/16/85 Frac perfs. 8828-897' w/38,000 gals. gelled lease crude and 70,000# 20/40 sand. Flow & swab test.
- 12/26-27/85 Run production equipment & set pumping unit.
- 12/30/85 Start pumping from perfs. 8820' to 9482'.