Form 9-331 Dec. 1973

## UNITED STATES Hand DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS

			Approved		
وت ت		Budge	t Bureau	No. 42-	R1424
5. LEAS					 -
6. IF IN	DIAN, ALL	OTTEE	OR TRIE	BE NAM	E
7. UNIT	AGREEM	ENT NA	ME		7
	ORLEAS ero Ri			1 .	<u>;</u>
9. WELL	. NO.			* .	:
10. FIELI Mescal	or will ero Es	Carpe	AME Bone	Spri	ng
11. SEC., AREA	١			A 64 8 8	EY OR
Sec. 1	3 T-18	<u>-</u> S, R	-33-E	- 1 - 1	
12. cour Lea	NTY OR P.	ARISH	13. ST NM	ATE -	<del>-</del>
14. API N	10.				
<b>15</b> . ELEV 40	ATIONS (	SHOW GR :	DF, KD	B, AND	WD)
		-			
(NOTE: R	eport resul hange on F	ts of mul orm 9–3	tiple com 30.)	pletion o	or zone
•			.1		

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)					
1.	oil well		gas well		other
2.	NAM Sun	E OF Exp	opera lorati	ror on 8	Production Co.

3. ADDRESS OF OPERATOR P.O. Box 1861, Midland, Texas 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17

below.) AT SURFACE: Unit Letter A 430' FNL & 900' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON\* (other)

BSEQUÉN	T REPORT OF: 🖰 😓
	**************************************
	2 19rus

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* MIRU XPert WS/POH w/rods & pump/ NU BOP/POH w/2-7/8 tbg w/pmpg set up/ 8/12/86

RIH w/BJ "PF" Tool on 2-7/8 tbg to 8740 load csg w/2% KCL/wash BS set I 8/13/86 8744--8766~w/50~bbls 2% KCL w/working thru perfs BJ spot 1500 gal 20%NEFE to PF Tool SICO Inject acid in perfs while round trip thru perfs AIR 1 BPM @ 2000 ISIP 1750 5 min 800 10 min 190 15 min SIP 80 / POH LD PF Tool/ RIH w/5-1/2 RDG on 2-7/8 tbg set PKR 8643

ND BOP NU wellhead ran paraffin knife cut paraffin to 1000' 8/14/86

8/15/86 No flow on /BJ Acdz BS set I 8744-8766 w/1000 gal 20% NEFE @ opsi @ 4 BPM ISIP vac POH / RIH w/2-7/8 tbg w/pmpg set up to 5456

Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct  SIGNED DE TITLE PROUNTING ASSISTANT DATE	3-20 -8(ō

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: