Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

	AT 001				
P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Por 2009		WELL API NO.			
P.O. Box 2088 DISTRICT II P.O. Drawer DD. Agrecia N.M. 28210 Santa Fe, New Mexico 87504-2088			30-025-29275		
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Azzoc, NM 87410			5. Indicate Type of		
			STATE X FEE 6. State Oil & Gas Lease No.		
OLD INDOVACE	IOCO AND SERVE				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					
			7. Lease Name or Unit Agreement Name N. HODDS (C.(SA) LINET.		
1. Type of Well:	TOTAL COOK PHOPOSALS.		N. HOBBS (G/S/ SECTION 33	A) UNIT	
MET X MET OVE	OTHER				
2. Name of Operator			8. Well No.	·	
Shell Western E&P Inc. 3. Address of Operator			234		
P.O. Box 576 Houston, TX 77001-0576			9. Pool name or Wildcat		
4. Well Location			HOBBS (G/SA)		
Unit Letter K : 137	72 Feet From The SOUTH	Line and	2563 Feet From T	he WEST	Line
Section 33					
	10. Elevation (Show whether	inge 38E DF, RKB, RT, GR, etc.)	NMPM LEA		County
	///// 3648' KB	•			
11. Check A	Appropriate Box to Indicate 1	Nature of Notice, R	eport, or Other I	Pata Pata	
NOTICE OF INT	ENTION TO:	SUB	SEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	_		
TEMPORARILY ABANDON	CHANGE PLANS	İ	 1	TERING CASING	
DINI OR ALTER CACING				LUG AND ABANDON	MENT [_]
CASING TEST AND C			MENT JOB		
OTHER:		OTHER: AT/INST	LARGER LIFT		X
 Describe Proposed or Completed Operati work) SEE RULE 1103. 	ions (Clearly state all pertinent details, an	d give pertinent dates, includ	ling estimated date of st	arting any proposed	
8-17 TO 8-21-92:					
POH W/PROD EQMT. ACD SA P	ERFS 4046' - 4224' W/2400	0 GAL 15% NEEE UC	INST DOOR TO		
(LARGER LIFT) & RTP.		O GAL 13% NEFE HC	INST PROD EQ	МТ	
I hereby certify that the information above is true	and complete to the heat of my brombotes and t	which			
$(/\mathcal{M})$	1 1		EAGUS		
SIGNATURE AND TO THE SECOND TO	mu mu	TECH. MANAGER	- ENVIR. ENG.	DATE10/23/92	2
TYPEORPRINTENE W. F. N. KELLE	XORF			TELEPHONE NO. 713	/870-379
(This space for State USRIGINAL SIGNED	RY JERRY SEXTON				
	SUPBRVISOR			^	n .c.
APPROVED BY	mu	E	<u> </u>	DATE OCT 2	7 '92