

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other

2. NAME OF OPERATOR

TXO Production Corp.

3. ADDRESS OF OPERATOR

900 Wilco Bldg. Midland, TX 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 2310' FNL & 330' FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other)

SUBSEQUENT REPORT OF:

☐

☒

☒

☐

☐

☐

☐

☐

☐

5. LEASE

NM-40452

6. IF INDIAN, ALLOTTEE OR TRIBE NAME.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sprinkle Federal

9. WELL NO.

3

10. FIELD OR WILDCAT NAME

Querecho Plains (Upper Bone Springs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 26, T-18-S, R-32-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3757' GL & 3768' KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-27-86 Rn 217 jts. 5-1/2" csg, 17# & 15.5#. Set @ 8710'.

Pump 500 gal. mud flush w/200 sx 50/50 POZ "H" 2%

CaCl. TD 7-7/8" hole @ 8710'.

3-28-86 TOC @ 7720'. WOCU

3-31-86 Bone Springs perfs 8502-8518. Perf w/4" gun, 5 holes.

4-02-86 Spt w/250 gal. 15% NEFE. Set pkr @ 8374' w/15,000#.

4-03-86 Bone Springs perfs 8541-8568. Perf w/4" gun, 7 holes.

Spt w/250 gal. 15% NEFE. Set pkr @ 8529' w/20,000#.

Rls pkr. Set pkr @ 8374' w/20,000#. Acdz w/2000 gal.

15% NEFE.

4-05-86 Frac w/39,000 gal. 40# gel. & 60,000# 20/40 snd.

4-07-86 Remove frac head. Install BOP. Set pkr @ 8374'. Test to 1500#. O.K. Install WH.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Cecilia Henderson TITLE Engineering Ass't DATE 4-10-86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

FILED FOR RECORD

Guo

*See Instructions on Reverse Side

APR 17 1986

CARLOS, NEW MEXICO