

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Mewbourne Oil Company		8. FARM OR LEASE NAME Federal "E"	
3. ADDRESS OF OPERATOR P. O. Box 7698, Tyler, Texas 75711		9. WELL NO. 12	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 330' FEL		10. FIELD AND POOL OR WILDCAT Querecho Plains - Upper Bone Springs	
14. PERMIT NO. API #30-025-29629		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 27-18S-32E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3752' GR		12. COUNTY OR PARISH Lea	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Production String</u>	<input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4/07/86 - Ran float shoe, shoe joint 43.84', float collar, 12 centralizers, 60 joints 5-1/2" 20# N-80 used 2398.45', 45 joints 5-1/2" 17# N-80 LT&C used 1936.86', 5 joints 5-1/2" 17# N-80 LT&C new 205.14', 106 joints 5-1/2" 17# N-80 LT&C used 4391.04', 2 joints 5-1/2" 20# N-80 LT&C new 80.51'. Total 9055.84'. Set at 9052'. Halliburton cemented with 535 sxs of HLC with 5# salt, 3/10% Halid 9 and 300 sxs of Class H with 5# salt, 3/10% Halid 9. PD to 9012' at 4:45 A.M. 4/7/86. Circ 0.

ACCEPTED FOR RECORD

[Signature]
APR 22 1986

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* TITLE Engineering Oprns. Secretary DATE April 18, 1986

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side