

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY HOLE		7. Unit Agreement Name
2. Name of Operator REGENCY PETROLEUM COMPANY OF NEW MEXICO		8. Farm or Lease Name STATE 32
3. Address of Operator 600 E. CARPENTER FRWY., SUITE 255 - IRVING, TX 75062		9. Well No. 1
4. Location of Well UNIT LETTER B 350 FEET FROM THE NORTH LINE AND 350 FEET FROM THE EAST LINE, SECTION 32 TOWNSHIP 18S RANGE 39E NMPM.		10. Field and Pool, or Wildcat HOBBS EAST <i>Blindby</i>
15. Elevation (Show whether DF, RT, GR, etc.) 3592.0' GR/3602.0' DF		12. County

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

DUMP 3 SACKS CEMENT ON CAST IRON BRIDGE PLUG AT 5825'  
SET CAST IRON BRIDGE PLUG AT 4330' (TOP OF SAN ANDRES).  
DUMP 3 SACKS CEMENT ON CAST IRON BRIDGE PLUG AT 4330'  
SET 25 SACKS CEMENT PLUG AT 3100' TO 2800' (TOP OF YATES)  
SET 25 SACKS CEMENT PLUG AT 1950' TO 1650' (ACROSS 8-5/8" SURFACE SHOE)  
SET 10 SACKS CEMENT PLUG AT SURFACE

\*FILL CASING WITH 10# BRINE MIXED WITH 25# JELL PER BARREL FROM  
LAST CAST IRON BRIDGE PLUG SET.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry D. Waller TITLE President DATE 3/14/87

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAR 1987

CONDITIONS OF APPROVAL, IF ANY: