

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-3801	
7. Unit Agreement Name	
8. Farm or Lease Name	
Buffalo "32" State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Buffalo (Yates)	
12. County	
Lea	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>	
<p>1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u></p>	
<p>2. Name of Operator</p> <p><u>M. Brad Bennett</u></p>	
<p>3. Address of Operator</p> <p><u>P.O. Box 2062 Midland, TX 79702</u></p>	
<p>4. Location of Well</p> <p>UNIT LETTER <u>M</u> <u>330</u> FEET FROM THE <u>south</u> LINE AND <u>330</u> FEET FROM</p> <p>THE <u>west</u> LINE, SECTION <u>32</u> TOWNSHIP <u>18S</u> RANGE <u>33E</u> NMPM.</p>	
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p> <p><u>3715.3 GR</u></p>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RU; Pull tubing; Spot 30 sx plug @ 3462'; Tagged plug; Spot 25 sx plug @ 1522'; Perf 5-1/2" csg @ 455' & squeezed w/110 sx; Set 10 sx plug @ surface; Installed P&A marker & rigged down. Hole was loaded with mud & all displacements with mud. NMOCC witness was Jack Griffin.

Baber Well Servicing in Hobbs, New Mexico performed plugging operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Individual</u>	DATE <u>10/27/86</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>DEC 3 1 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
OCT 28 1986
HOBBS-CLE
HOBBS-CLE